

2nd Year Maintenance

31

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maint. of Road from					
Toi (Piradalgach Road) to Pipra					
Mozz Pala					
Agency - Sri Babbar Pwari					
By Do - 139 SRD / MMDSY/2021-2022					
Date of Start - 28.07.2021					
Actual completion - 10.05.2022.					

Record Entry

① Restoration of Rain

Cuts - Do -

$$4 \times 4.60 \times 1.60 \times 0.30 = 8.83$$

$$3 \times 4.08 \times 1.15 \times 0.20 = 2.80$$

$$11.63 \text{ m}^2$$

② Maint. of Earthen

Shoulder - Do -

$$4 \times 4.60 \times 1.80 = 33.12$$

$$6 \times 3.50 \times 1.50 = 31.50$$

$$4 \times 5.60 \times 1.80 = 40.32$$

$$6 \times 3.90 \times 1.90 = 44.46$$

$$5 \times 3.60 \times 1.40 = 25.20$$

$$4 \times 6.30 \times 1.65 = 41.58$$

$$6 \times 3.90 \times 1.85 = 43.29$$

Continuation

$$259.49 \text{ m}^2$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		B/r		B	41168.00
Add G.S.P.	0.12%			B	4940.00
Add L.C.	0.1%			B	412.00
Add S.F.				B	232.00
Total				B	46752.00
Less 0.05%				B	-23.00
Total				B	46729.00

As per
10/08/24
J.E.

Per
10/08/24
M

Material used:-

- ① Earthwork - 89.471 m³
- ② Bitumen - 22.00 kg (22 kg)
- ③ Emulsion - 08.00 kg (08 kg)
- ④ Stone chips - 0.274 m³
- ⑤ Gravel sand - 0.061 m³

As per
10/08/24
J.E.

Per
10/08/24
M

Continuation