

2nd year Maintenance

38

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Const/ Maint of road from Muijunga Laxman Rai Ke ghar to Mai Road Tak					
Agency - Sri chandrabhushan Basad					
Agreement No - 83/8BD/2020-21					
Date of work order - 26-02-2021					
Actual Completion date - 24-02-2022					

Record Measurement

Item No (I) Restoration of

rain culs

$$1 \times 6.15 \times 1.05 \times 0.30 = 1.93 \text{ m}^3$$

$$2 \times 5.25 \times 1.10 \times 0.30 = 3.15 \text{ m}^3$$

$$1 \times 7.75 \times 0.80 \times 0.30 = 1.86 \text{ m}^3$$

$$3 \times 4.50 \times 0.75 \times 0.30 = 3.04 \text{ m}^3$$

$$4 \times 2.25 \times 0.90 \times 0.30 = 2.43 \text{ m}^3$$

$$1 \times 8.90 \times 1.05 \times 0.30 = 2.80 \text{ m}^3$$

$$3 \times 2.75 \times 0.95 \times 0.30 = 2.35 \text{ m}^3$$

$$2 \times 4.25 \times 1.05 \times 0.30 = 2.68 \text{ m}^3$$

20.24 m³

Limit - 20.08 m³

Continuation

Continuation