

4th Year Maintenance

63

sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work Name—	Ayodhya Durgam				
	Sahilpalli NH102. Rewa Road tak—				
Agency Name—	Mamaji Kumar Singh				
Agreement No—	150/530/2018-19				
Date of Start—	08/03/2019				
Date of actual Completion—	15/03/2020				
(1)	Restoration of rain cuts—				
	10X	9.0X	0.75	X0.30	20.25 m ³
	7X	6.0X	0.90	X0.35	13.23 m ³
	8X	5.0X	1.125	X0.30	13.5 m ³
	12X	4.50X	0.75	X0.30	12.15 m ³
	11X	3.0X	1.20X	0.35	13.86 m ³
	9X	4.0X	1.0X	0.30	10.8 m ³
	6X	2.5X	0.80X	0.30	3.6 m ³
	10X	6.0X	0.75X	0.35	15.75 m ³
	8X	5.5X	0.90X	0.30	11.88 m ³
	10X	6.5X	0.75X	0.35	17.06 m ³
	Limit = 131.63 m ³				132.08 m ³
(2)	Maintenance of earthen shoulder—				
	12X	3.0X	0.75		27.0 m ²
	4X	15.0X	0.90		54.0 m ²
	6X	30.0X	1.0		180 m ²
	9X	7.0X	0.75		47.25 m ²
	12X	15.0X	0.95		171.0 m ²
	10X	20.0X	1.120		224.0 m ²
	6X	11.0X	1.20		79.2 m ²
	8X	10.0X	0.85		68.0 m ²
	6X	11.0X	1.0		66.0 m ²
	2X	Continuation 6.0X1.0			16.0 m ²
					730.85 m ²

Abstract of Cost -

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of rain culv.					
THBP-63		131.63 m ²			
		@ Rs 380.58/m ²			50096 =
(2) Maintenance of earthen shoulder					
THBP-63		730.85 m ²			
		@ Rs 58.60/m ²			42828 =
(3) Repair to pot holes mix Seal surface					
THBP-64		151.95 m ²			
		@ Rs 254.34/m ²			38647 =
(4) Patch repair on already filled Pot holes					
THBP-64		152.30 m ²			
		@ Rs 309.40/m ²			47122 =
(5) Maintenance of horse pipe culverts					
THBP-64		6 No			
		@ Rs 117.00/each			6702 =
(6) Maintenance of slab type culverts					
THBP-64		12 No			
		@ Rs 2309.03/each			27708 =
(7) Maintenance of road sign					
THBP-64		2.84 Km			
		@ Rs 1074.51/Km			3052 =
(8) Maintenance of 200 m and Km stone					

Continuation

THBP-64- 2.84 Km
 @ Rs 735.27/Km — 2088 =
 ₹ 218243 =

Continuation