

5th Year maintenance

87

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Pradhikar vidyalaya Margi J. V. N. N. N. Pradhikar mantri Sadak to Margi Jagdish Lote hieldgare Tal. P. B. Chamu					
2. Agency: Jadhavsinh K. Singh					
3. Agreement No: 57/3120/2018-19					
4. Actual ch. of completion 19.05.2019					
— measurement on below —					
① Restoration of rain culb with soil - culb					
1x 20.50 x 0.90 x 0.30 = 5.535					
7x 20.50 x 0.90 x 0.30 = 38.745					
1x 18.90 x 0.80 x 0.30 = 4.536					
8x 30.00 x 0.75 x 0.30 = 54.0					
6x 30.00 x 0.68 x 0.30 = 36.72					
1x 20.90 x 0.58 x 0.30 = 3.636					
2x 18.90 x 0.65 x 0.30 = 7.371					
5x 30.00 x 0.65 x 0.30 = 29.25					
1x 2.60 x 0.50 x 0.30 = 0.39					
1x 5.90 x 0.45 x 0.30 = 0.729					
					Qty = 180.912m ³
					say Qty = 180.43m ³
② maintenance of earthen					
2. Shoulder culb					
1x 20.50 x 0.90 = 18.45m ²					

Continuation

C.O. Qty = 18.45m²

P. 730.

Continuation