

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
3rd year maintenance				
H/W :- Repair of road from				
Relative Priority to Relative				
Order				
H/A :- SRI sundar 12. Ras.				
A/HO :- 335B.D/2013 - 2019				
Date of actual completion :- 28-02-2020				
Date of Measurement :-				
Details of Work :-				
Item No (1) :- Restoration				
of drain cuts with soil				
10 x 30.00 x 1.05 x 0.30 =				94.50 M ³
3 x 30.00 x 1.05 x 0.30 =				28.35 M ³
1 x 5.00 x 1.05 x 0.30 =				1.58 M ³
				<u>124.43 M³</u>
				124.43 M ³
Item No (2) :-				
10 x 30.00 x 1.10 =				330.00 M ²
10 x 30.00 x 1.10 =				330.00 M ²
1 x 30.00 x 0.95 =				28.50 M ²
				<u>688.50 M²</u>
Item No (3) :- Repair of pot				
holes filled with 25MM WBM				
02 x 12.00 x 1.80 =				43.20 M ²
05 x 15.00 x 0.50 =				37.50 M ²
01 x 11.00 x 1.00 =				11.00 M ²
				<u>91.70 M²</u>
Item No (4) :- Patch repair				
over filled pot holes				
with 20MM M.S.S				

Continuation

Dry Lide Item No (3) ie = 91.70 M²

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
			B/F	P _a	145140 = 0
Station (5) - Maint. of H.P					
Culverts					
Qty vide T.M.B P/Ho (52)					
06 Nos @ Rs 1131.64/mo				P _b	6790 = 0
Station (6) - Maint. of road					
Sigds					
Qty vide T.M.B P/Ho (52)					
0.26 K.M @ Rs 1087.62/KM				P _b	286 = 0
Station (7) - Maint. of 200m					
and K.M stone					
Qty vide T.M.B P/Ho (52)					
0.32 K.M @ Rs 585.61/KM				P _b	185 = 0
Station (8) - Cutting of branches of tree					
Qty vide T.M.B P/Ho (52)					
03 Nos @ Rs 107.48/mo				P _b	322 = 0
Station (9) - White washing					
two coats plaster wall					
Qty vide T.M.B P/Ho (52)					
126.00 M ² @ Rs 16.48/M ²				P _b	2076 = 0
					154799 = 0
Less 10% below agg. cost ($\Rightarrow$)				P _b	15480 = 0
				P _b	139319 = 0
H/P					
25/02/23					
A.E.					J.E

Continuation