

1st Year No 30

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

① N/W Hammer to Kundera, Ghat 1/2
Kundera, Kundera

② N/A Rambalala Rant

③ N/A N/A 1/2 74/201-22

④ Actual of complete 21-09-22

① Restoring canal

17 x 2.4 x 0.95 x 0.90 = 34.88m

Ltd 33.87m

② Rebuilding earth wall

7 x 30 x 0.90 = 189.0m²

Ltd 188.16m²

③ Repair to pot hole

1 x 7.8 x 1.2 = 9.36m²

1 x 3.95 x 1.6 = 6.32m²

15.68m²

④ 7. Rebuilding 470 - 5m

⑤ Rebuilding culvert (slab)

three x 2 = 4m²

⑥ Rebuilding 200m x 100m

cc 687
B.T 318
0.985 km

⑦

⑧

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of sandal					
T.M.B. P(30) 23-87m					
@ R 404 = 08m ²					R 13,686 ~
(2) Mending of earthen Shovel					
T.M.B. P(30) 188-16m ²					
@ R 60228/m ²					R 11,342 ~
(3) Repair to pot hole					
T.M.B. P(30) 1568m ²					
@ R 2652/m ²					R 4,155 ~
417 Mending of H.P. cum					
T.M.B. P(30) 510					
@ R 1166-88 / each					R 5833 ~
518 Mending of slab cum					
T.M.B. P(30) 410					
@ R 2394 = 96 / each					R 9580 ~
6110 Mending of room cum & kitchen					
T.M.B. P(30) 0.9851m ²					
@ R 748 = 22 / each					737 ~
					R 45,333 ~
Mattress					
(1) 1st - 52.69m ²					
(2) 2nd - 0.43m ²					
(3) 3rd - 0.038m ²					
4/10/23 JEI/Name 4/10/23 Name					