

5th year maintenance

39

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of Road: <u>manikpur vajhadi</u>					
Road from Virpur to Chakdavan					
Total under survey					
2. Name of Agency: <u>Ashish Bhatnagar</u>					
3. Agreement No. <u>23/SBD/2018-2019</u>					
4. Approval Date: <u>10.07.2018</u>					
5. Actual date of completion: <u>05.10.2018</u>					
— measurement is below					
① Restoration of main cuts					
with 80% - 100%					
1x 20.50 x 0.60 x 0.30 = 3.69					
1x 18.90 x 0.60 x 0.30 = 3.402					
1x 20.50 x 0.75 x 0.30 = 4.635					
1x 18.90 x 0.72 x 0.25 = 3.402					
1x 20.60 x 0.65 x 0.30 = 4.284					
2x 20.60 x 0.60 x 0.30 = 7.416					
1x 18.90 x 0.68 x 0.30 = 3.855					
1x 10.50 x 0.60 x 0.25 = 1.575					
1x 5.50 x 0.62 x 0.25 = 0.852					
					Qty = 33.111 m ³
					Say Qty = 32.81 m ³
② Maintenance of earth					
shoulder - 100%					
1x 20.50 x 0.65 = 13.325					
1x 18.90 x 0.70 = 13.23					
1x 20.60 x 0.58 = 11.948					

Continuation

$$C.O. Qty = 38.53 m^3$$

P.T.O.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ maintenance of 5 pipe culvert					B.P.R. 90/101 = 4
					Qty = 2.0 Nos wide
					This page ④
					Item No ⑤
⑥ maintenance of 6 slab type culvert					@ Rs 1107 = 34 / each = 2209 = 00
					Qty = 2.0 Nos wide
					This page ④
					Item No ⑥
⑦ maintenance of 8 8cm stone culvert					@ Rs 2287 = 21 / each = 457920
					Qty = 0.360 km wide
					This page ④
					Item No ⑦
⑧ maintenance of 9 15cm stone culvert					@ Rs 675 = 29 / 15m = 293 = 00
					Rs 47127 = 00
					Less 10.0% below = 4713 = 00
					Rs 42419 = 00
10/11/23 10/12					
					Akumari 30/5/24 AK

Continuation