

5th year maidene work.

51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/A - Baranwada main work					
Pay ke change do chausina					
manavdar bah ke glassble					
N/A - Sarkar Kaur Rajar					
N/A - 5/12/2018					
Actual date of work - 3.12.2018					
(Measurement)					
① Restoration of main gate					
	2	30	1.80	0.20	16.20 m ³
	9	30	1.80	0.20	14.58 m ³
	6	12	1.125	0.30	24.30 m ³
					54.68 m ³
② Maintenance of earth shoulder					
	2	30	0.90		54 m ³
	9	30	1.80		48.60 m ³
	8	12	1.125		108 m ³
	5	15	1.125		74.375 m ³
					304.575 m ³
③ Maintenance of picture surface					
	9	3.50	2.25		70.875 m ³
					70.875 m ³
④ Maintenance of picture surface					
	3	3.50	2.25		70.875 m ³
					70.875 m ³

Continuation