

4th Year Maintenance

21

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Koirgama- Ganga Sirisiya Path in Koirgama to Ganga Sirisiya ke beech Path nirman under NABARD					
Agency- Vijay Coirsi					
Agreement No- 5398D/2018-19					
Date of start- 16/01/2019					
Date of completion- 15/10/2019					
Actual date of completion- 15/09/2019					
4 th Year Maintenance? 16/09/2022					
Period 15/09/2023					
① Restoration of Raincuts					
1 X	8.40	X 1.20	X 0.25	=	2.40m ³
2 X	5.40	X 1.15	X 0.25	=	2.87m ³
2 X	9.40	X 1.25	X 0.30	=	6.75m ³
1 X	6.50	X 1.10	X 0.30	=	2.14m ³
1 X	8.50	X 1.25	X 0.30	=	3.19m ³
2 X	6.40	X 1.20	X 0.25	=	3.60m ³
3 X	7.40	X 1.20	X 0.30	=	7.56m ³
3 X	9.40	X 1.25	X 0.30	=	10.12m ³
1 X	7.50	X 1.28	X 0.25	=	2.40m ³
1 X	6.40	X 1.30	X 0.30	=	2.34m ³
1 X	10.40	X 1.25	X 0.25	=	3.12m ³
2 X	8.40	X 1.28	X 0.25	=	5.12m ³
2 X	10.10	X 1.15	X 0.30	=	6.97m ³
					58.58m ³

Continuation

Abstract of cast

24

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cut					
Q-VTIBP21① = 58.88H					
e R - 365.25/H - R -					21396=
② Maintenance of earthen Shoulder					
Q-VTIBP22② = 325.48H					
e R - 54.37/H - R -					17696=
③ Maintenance of bituminous Surface road					
① Repair to foot path					
Q-VTIBP23④ = 69.37H					
e R - 285 = 84/H - R -					19829=
(ii) Maintenance of width road					
Q-VTIBP23⑥ = 69.37H					
e R - 374.90/H - R -					26007=
(iii) Patch repair:-					
Q-VTIBP23⑥ = 69.37H					
e R - 270.08/H - R -					18735=
④ Maintenance of slab culvert					
Q-VTIBP22③ = 1N					
e R - 2336.81/each R -					2337=
⑤ White washing on bridge					
Q-VTIBP22⑤ = 13.88H					
e R - 16.80/H - R -					233=

Continuation

106233=

105942=

Continuation