

Second Year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
Head (mmG. 27) 16m					
Name of work: Construction of head from					
Debari more for Dikari.					
Agency: M/c progressive construction					
Ag. No. - 011 / SBD / mmasy / 2020-21					
Date of start					
Date of Comp.					
Det. of Actual Comp.					

Measurement					
(1)	Restoration of land				
	Barry acclis Soil				
	etc etc				
2x	9.2	1.82	0.3	= 10.04 m ²	
5x	10.20	1.63	0.3	= 15.42 m ²	
4x	9.2	1.75	0.3	= 20.32 m ²	
	Total:				45.83 m ²
	Limit:				45.23 m ²
(2)	making up of Ram				
	Repair of Rub holes				
	Shoulder & riprap				
	filled with 5mm				
	cracks seal from the				
	etc etc				

Continuation

Continuation