

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मधेपुरा

पत्रांक- 1482 अनु0

दिनांक- 13/6/24

प्रेषक,

ई0 विद्यानन्द प्रसाद,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधेपुरा।

सेवा में,

नोडल पदाधिकारी,
3054 एम.आर. कोषांग,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय- MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों के भुगतान हेतु अधियाचना के संबंध में।

प्रसंग- भवदीय पत्रांक 113 अनु0 दिनांक 10.01.2020

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल मधेपुरा अन्तर्गत MR (3054) under New Maintenance Policy- 2018 योजना के पथ में पूर्ण कराये गये कार्यों का भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

- अनु0- 1. अधियाचना विहित प्रपत्र में।
2. Recorder IRI की प्रतिहस्ताक्षरित प्रति।

विश्वासभाजन

(ई0 विद्यानन्द प्रसाद)
कार्यपालक अभियंता,

13/6/24
13/6/24

Form GFR 19- A

(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month of 13.06.2024
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	New Maintenance Policy 2018	Letter No 56 Dated 12.08.2020 Letter No 86 Dated 11.12.2020	Rs 211.66000 Vide Letter No :- 74 Dated 03.06.2024	Certified that out of RS 12271.69349 lacs of grants in aid sanctioned during the Years up to 2024-25 in favour of Executive Engineer, RWD Works Division Madhepura under this Department, a sum of Rs 12137.58789 lacs has been utilized for the purpose of New_MR Scheme remaining 134.105600 unutilized at the end of the period under report.
		Total :	211.66000	


Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction material have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works


D.A. 63/06/24
RWD works Division
Madhepura


13/6/24
Executive Engineer
RWD works Division
Madhepura

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Madhepura

Sl.No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative		Agreement Amount		Agreement Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percent	Previous Total Allocated Amount (l Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	RM/MA/MAD/23/0014	NH106 Singheshwar Durga Asthan To Rahmani Tola	21004712039	1447 / 28.02.2023	1.050	61.72	39.22453	13.20601	28 MBD/2023-24	04.05.2024	14.05.2024	3423.50	25mm	5%	0.00	0.00	39.22000	Complete

[Signature]
13/6/24

Divisional Accounts Officer
RWD Works Division
Madhepura

[Signature]
13/6/24

Executive Engineer
RWD Works Division
Madhepura

[Signature]
13/6/24

Name Of Road :- NH106 Singheshwar Durga Asthan To Rahmani Tola Name Of Contractor :- Shiv Krishna Builders Private Limited

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	CATEGORY	IRI	Latitude	Longitude	Event
		No.					ROAD				
05/04/24	11:24:31	23	0.1	200	30.3	3000	G	3490	25.986053	86.79298	Normal
05/04/24	11:25:6	23	0.1	170	20.2	3500	G	3750	25.986185	86.792353	Curve
05/04/24	11:25:6	23	0.1	230	20.2	3400	G	3431	25.984325	86.791857	Normal
05/04/24	11:25:41	23	0.1	220	10.1	3300	G	3318	25.987103	86.790278	Normal
05/04/24	11:25:41	23	0.1	180	10.1	3700	G	3863	25.986732	86.789901	Culvert
05/04/24	11:26:16	23	0.1	220	20.2	3300	G	3318	25.986932	86.788349	Curve
05/04/24	11:26:16	23	0.1	240	20.2	3400	G	3545	25.986069	86.787955	Normal
05/04/24	11:26:52	23	0.1	300	20.2	3000	G	3226	25.984107	86.78763	Normal
05/04/24	11:26:52	23	0.1	200	10.1	3000	G	3090	25.982799	86.78814	Normal
05/04/24	11:27:27	23	0.1	210	10.1	3100	G	3204	25.982832	86.787125	Normal
Average IRI								3423.50			

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

$$Y = 0 * X^2 + 1.136 * X - 181$$

$$X = 2100$$


$$Y = 2204$$

06/06/24
J.G.

06/06/24
w

06/06/24

File : F:\STECO-USB-GPS V1_1\18050845.Xls, Section No. :23, Eqn : $Y = 0 * X^2 + 1.136 * X - 181$
 Name of Customer : Shiv Krishna Builders Private Limited, Name of Work/ Road : NH106 Singheshwar Durga Asthan



[Signature]
 06/06/24

[Signature]
 06/06/24

[Signature]
 06/06/24