

Name of work

Habitation to Habitation

**Schedule XLV Form No. 134.**

Agency -- Sanjay (K.P.S.G.) Executive Engineer  
Breach R.W.D. Works Division  
Railway

**DIVISION**

A.E. Narhat

**SUB-DIVISION**

M.B. No. 1064

**Measurement Book**

## Sch. XLV-Form No. 134

| Particulars                       | Details of actual measurement |    |    |           | Contents of area |
|-----------------------------------|-------------------------------|----|----|-----------|------------------|
|                                   | No.                           | L. | B. | D.        |                  |
| M/Rat- consd. of Road from Habit. |                               |    |    |           |                  |
| ation to Habitatio.               |                               |    |    |           |                  |
| Agency- Sangay Kumar              |                               |    |    |           |                  |
| Afno 109/HMSY/SBD/2020-21         |                               |    |    |           |                  |
| Actual dt of completion           |                               |    |    | 31/3/2022 |                  |
|                                   |                               |    |    | 15/2/22   |                  |

## (1) Restoration of drain culb-

|    |      |   |      |   |      |                      |
|----|------|---|------|---|------|----------------------|
| 4x | 3.75 | x | 1.35 | x | 0.30 | 6.07 m <sup>3</sup>  |
| 6x | 5.10 | x | 1.20 | x | 0.30 | 11.02 m <sup>3</sup> |
| 5x | 4.70 | x | 1.50 | x | 0.30 | 10.57 m <sup>3</sup> |
| 3x | 6.25 | x | 1.30 | x | 0.30 | 7.31 m <sup>3</sup>  |
| 4x | 4.50 | x | 1.50 | x | 0.30 | 8.10 m <sup>3</sup>  |
| 5x | 5.20 | x | 1.30 | x | 0.30 | 10.14 m <sup>3</sup> |
|    |      |   |      |   |      | 53.21 m <sup>3</sup> |

## (2)

Maintenance of earthen

Shoulder.

|    |    |       |   |      |   |                             |
|----|----|-------|---|------|---|-----------------------------|
| 2x | 4x | 30.00 | x | 1.10 | = | 264.00 m <sup>3</sup>       |
| 2x | 2x | 30.00 | x | 0.80 | = | 48.00 m <sup>3</sup>        |
|    |    |       |   |      |   | 312.00 m <sup>3</sup>       |
|    |    |       |   |      |   | Unit. 310.50 m <sup>3</sup> |

## (3) Maint of the culvert - 01 No

## (4) Maint of R/S gate - 0.920 k

## (5) Maint of 200 meter - 0.138 kg

## (6) Trimming of grass &amp; weeds

|    |    |       |   |      |   |                       |
|----|----|-------|---|------|---|-----------------------|
| 2x | 4x | 30.00 | x | 1.20 | = | 288.00 m <sup>3</sup> |
| 2x | 3x | 30.00 | x | 1.10 | = | 198.00 m <sup>3</sup> |
| 2x | 4x | 30.00 | x | 1.15 | = | 276.00 m <sup>3</sup> |
|    |    |       |   |      |   | 762.00 m <sup>3</sup> |

Continuation

## Sch. XLV-Form No. 134

| Particulars                          | Details of actual measurement |    |    |    | Contents of area     |
|--------------------------------------|-------------------------------|----|----|----|----------------------|
|                                      | No.                           | L. | B. | D. |                      |
| ① White wash of Para Pol.            |                               |    |    |    |                      |
| 1x 3.60 x 0.60 = 2.16 m <sup>2</sup> |                               |    |    |    |                      |
| 2x 3.60 x 0.40 = 2.88 m <sup>2</sup> |                               |    |    |    |                      |
| 1x 0.40 x 0.60 = 0.24 m <sup>2</sup> |                               |    |    |    |                      |
|                                      |                               |    |    |    | 12.48 m <sup>2</sup> |
| <del>Adhmon</del><br>05/02/24<br>J.E |                               |    |    |    |                      |
| <del>Adhmon</del><br>05/02/24<br>A.E |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |
|                                      |                               |    |    |    |                      |

| ABSTRACT OF COST               |  |  |  |        |
|--------------------------------|--|--|--|--------|
| ① Restoration of rain cul      |  |  |  |        |
| 53.21 m <sup>3</sup> (MSP 39)  |  |  |  |        |
| at 773.74/m <sup>3</sup> —     |  |  |  | 41181~ |
| ② Manl of earthen shoulder     |  |  |  |        |
| 310.50 m <sup>3</sup> (MSP 39) |  |  |  |        |
| at 57.92/m <sup>3</sup> —      |  |  |  | 17984~ |
| ③ Manl of P.C. wall            |  |  |  |        |
| 0.1 m <sup>3</sup> (MSP 39)    |  |  |  |        |
| at 1130.67 —                   |  |  |  | 1131~  |
| ④ Manl of R.L. sign            |  |  |  |        |
| 0.920 m <sup>3</sup> (MSP 39)  |  |  |  |        |
| at 1077.81 —                   |  |  |  | 992~   |
|                                |  |  |  | 61288~ |

Continuation

