

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/Road. maint of Rd. from Parvathy (Kersection) to Akari Perapiga Road -					
Agency	Sanjay Kumar				
Approx	03/CAD/MMSY/ 2019-20				
Actual dt of Complete.	21/02/2020				
(1) Restoration of rain cul.					
4x	2.60	x 1.40	x 0.30		4.37 M ³
5x	2.30	x 1.50	x 0.30		5.17 M ³
3x	3.10	x 1.30	x 0.30		3.63 M ³
4x	2.70	x 1.50	x 0.30		4.06 M ³
5x	2.70	x 1.40	x 0.30		5.67 M ³
3x	3.25	x 1.60	x 0.30		4.69 M ³
					28.38 M ³
				Cum —	28.35 M ³
(2) Maintenance of earthen					
Shoulder —					
2x	30.00	x 1.00			120.00 M ³
2x	15.00	x 1.00			30.00 M ³
					150.00 M ³
(3) Maintenance of 4pc cum					
					0.1 M
(4) Maintenance of Rd Spurs					
					0.350 M
Inkman 5/2/20 J.E.					

Continuation

ABSTRACT OF COST

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of soil					
Cuts soil - L					
28.35 m ³ (TM BP 41)					
Ct 380.52/m ³					10788.
② Maintenance of earth					
shoulder -					
150.10 m (TM BP 41)					
Ct 57.53/m ²					8629.
③ Maintenance of HP					
Culvert -					
0.1 m (TM BP 41)					
Ct 1117.00/m					1117.
④ Maintenance of P					
Sign -					
0.350 m (TM BP 41)					
Ct 1079.51/m					376.
⑤ Maint of 200 M stem					
- do -					
0.063 m (TM BP 42)					
Ct 777.69/m					49.0
⑥ Tearing of ground					
- do -					
282.10 m ² (TM BP 42)					
Ct 218/m ²					615.
⑦ Working of Pavement					
walk -					
6.56 m ² (TM BP 42)					
Ct 17.12/m ²					113.
Continuation					21697.0

Material systems

① E/w 43.78 m

~~Abm~~
24/24
S.E

Abm
24/24
AE