

2nd year Maintenance

69^x

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road:- Lalganj					
Madarna road ke Toth ka					
Paswan toli Hote huye					
To Purantend Samudraile					
Bhawan via Samaspura					
Mushar Besti.					
Agency:- Rajeev kumar					
Agreement No-155BD/2019-20					
Actual Date of comp. 5/7/2020					
1 Restoration of					
rain culs.					
17 x 2.9 x 1.1 x .30 = 16.27					
8 x 4.1 x .95 x .30 = 9.34					
6 x 3.5 x .65 x .30 = 4.09					
11 x 3.3 x .90 x .25 = 8.16					
13 x 4.5 x 1.9 x .30 = 33.34					
7 x 2.9 x .65 x .30 = 3.95					
12 x 3.7 x .95 x .30 = 12.65					
8 x 4.1 x .75 x .30 = 7.38					
11 x 3.9 x .85 x .30 = 10.94					
21 x 2.9 x .65 x .30 = 15.48					
15.56					
8 x 4.4 x .75 x .30 = 7.92					
14 x 3.7 x .85 x .30 = 13.20					
13 x 3.8 x 1.1 x .30 = 16.30					
17 x 3.85 x .95 x .30 = 18.65					
					177.853
limet Qty = 170.40 m ³					

Continuation

B F P-165726=

8 culting & branch
of tree

8 has vine P- 71

@ 106.12 / each P= 8492

9 culting & shrub

36 has vine P- 71

@ 6.5 / each P= 234. =

10 Trimming & grass

15.98 m² vine P- 71

@ 2.17 / m² P= 35. =

11 white washing
of parapet -

21 m² vine P- 71

@ 15.94 / m² P= 335.00

P=1651792

Less 10% below P=16517.9

P= 148661 =

~~Underhand~~
09/08/22 AE P=

9/7/22
J-E

CSP
9/7/22
19/6/24

Material Statement

Earth - 291 m³

Bitumen 59-0.24 m²

Emulsion 1036 m²

Continuation

ph 9/7/22
J-E