

Sch. XLV - Form No. 154		Details of actual measurement				Contents of area
Particulars	No.	L	B	D		
Name of work - maintenance of road and c.d.						
Work from Malpath to						
Hannu mantal phareli 59						
under G.T.S.M.S						
Agency: B.N. Engr Pn. Des						
Agreement No. 24 SBP/2018-19						
Date of 3rd year maintenance start - 20/11/2021						
Date of 3rd year maintenance complete - 20/11/22						
Date of entry - 17.11.2022						
(1) Restoration of minor bent						
with soil masonry after						
E.I.						
	2+21	9.857	1.125	0.30	13.30 M ³	
	2+44	8.257	1.125	0.30	23.62 M ³	
Continuation						36.92 M ³

Sch. XLV - Form No. 134

Sch. XLV - Form No. 134		Details of actual measurement				Contents of area
Particulars	No.	L.	B.	H.		
ABSTRACT OF COST						
3rd year maintenance.						
(11) replacement of damaged bearing						
cost sand mortar and plaster						
atb vide T.M.B.P. 40(11)						
25.05 m ³ @ 360.32/m ³						30645.00
(12) making up bearings shoulder						
as per E.H.						
atb vide T.M.B.P. 43(2)						
472.50 m ² @ 51.95/m ²						24546.00
(34) maintenance of H.P. culvert						
as per E.H.						
atb vide T.M.B.P. 40(3)						
02 No. @ 1032.18/No.						2144.00
(47) maintenance of road						
as per E.H.						
atb vide T.M.B.P. 40(4)						
1.950 km @ 1086.35/km						2117.00
(58) maintenance of 20m and						
10m stone as per E.H.						
atb vide T.M.B.P. 44(5)						
0.270 km @ 711.40/km						192.00
(69)(i) cutting of roadside trees						
and shrubs as per E.H.						
atb vide T.M.B.P. 44(6-i)						
02 No. @ 101.44/No.						710.00
(710)(ii) cutting of shrubs from roadside						

Continuation

100-60258-00

Continuation

100-60258-00

[illegible]

GTSNY - નસપદ્દી સે દુરુગાન ટોન વાળોવાનું.

Schedule XLV-Form No. 134

GTSNY

_____ યુનિટ DIVISION

_____ યુનિટ SUB-DIVISION

MEASUREMENT BOOK

40
18-19

M.B. No-40
18-19

બીજા ૨૦ નાં દુરુગાન ટોન