

1mg5y-(16222)

(32)

(32)

M.B.N.-379
19-20

Schedule XLY-Form No. 134

2001241 (4-24191.31m1241.416201241-84-
327-000-

पुनः प्रवेश

DIVISION

पुनः प्रवेश

SUB-DIVISION

M.B.N.O - 3.849-379

Measurement Book

पुनः प्रवेश

(32)

प्रमाणित किया जाता है कि इस
मापी पुस्त में मशीन द्वारा अंकित
कुल - 100 (रुफ वॉ) पत्तों हैं जिसे
श्री-अश्विन्द कुमार, सहायक अभियंता
ग्रामीण कार्य विभाग, कार्य अवर
प्रमंडल, चौधम वॉ निर्गत किया
जाता है।

10-12-19
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
प्रमंडल-गोगरी
Back
10-12-19

Sch. XLV - Form No. 134

प्रमंडल, गोगरी DIVISION
अवर प्रमंडल, चौधम SUB-DIVISION

Measurement Book

No. .

Name of officer _____

Date of first entry _____

Date of last entry _____

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - construction					
of road from Tekaniza					
to Sarsawa, Gulare,					
Soharba Thutti Lak.					
27580/2016-17.					
Agreement No: - Mahendra Kumar					
Agency: - Sri Mahendra Kumar					
Date of start: - 10.12.2016.					
Date of completion: - 29.12.17.					
Time extension Approved: - 31.07.19					
Actual date of completion: - 31.07.19.					
Further Measurement -					
work done					
Nil.					
24.02.2020					
JE					
12th & final bill: -					
Abstract of cost					
① Provision and bidding of					
bench mark pillars - - -					
16.00 Nos. (vide page-88, MB-185)					
@ Rs. 1918.24/each = Rs. 30692.00/-					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1 x 11.20 x		0.90		10.0	8 m ²
1 x 5.70 x		2.90			16.53 m ²
18 x 3.57 x		1.60			100.80 m ²
11 x 2.60 x		1.70			48.62 m ²
					192.83 m ²

⑤ Maintenance of CD

WSSS - de - 2

94-5 x 2,

19/06/22
JZ

19/06/22
A.E

3rd year Maintenance

ABSTRACT OF COST

① Restoration of rain cuts

Borms with 1001 - de - 2

648.60 m³ - TMBP - (22)

@ 1/321 = 51/m² - 20853/20

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Making up of Barm					
Shoulders stripping excess					
Soil from the shoulders					
do — do — 06					
1884.00m ² — Tmep — ②②					
@ 49 = 07/m ² — 92448 =					
③ Patch repair over					
At holes with 20mm					
Premix Carpet with					
Seal Coat do —					
190.04m ² — Tmep — ②③					
@ 274 = 48/m ² — 52162 =					
④ Patch repair over					
bituminous surface with					
20mm Premix Carpet with					
Seal Coat do —					
192.83 m ² — Tmep — ②④					
@ 274 = 48/m ² — 52928 =					

Continuation

~~19/06/22~~
~~17/08/22~~
~~CEP~~
~~ST/2024~~
~~EE~~
~~A-E~~

Masters of the Element

①BW	-	931.20 m	
-----	---	----------	--

② Stone chips -	10.34 m ²
-----------------	----------------------

④ Course end - 2:30 PM

① Bitumen	-	819 kg
-----------	---	--------

19/06/22
JE

Continuation