

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, पुपरी (सीतामढ़ी)

पत्रांक :- 1501 पुपरी, दिनांक :- 20/06/2024
प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, पुपरी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास एजेंसी,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:- नई अनुरक्षण नीति 2018 MR (3054) योजना के अन्तर्गत पंचवर्षीय अनुरक्षण कार्य के लिए निधि उपलब्ध कराने के संबंध में।

प्रसंग:- अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार, पटना के पत्रांक-मु0अ0-4(मु0)
3054-04-229/2021-1135 (अनु0)/पटना, दिनांक-09.03.2022

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र में दिये निर्देश के आलोक में नई अनुरक्षण नीति 2018 अन्तर्गत पथों का अनुरक्षण की राशि के आवंटन हेतु विहित प्रपत्र में अंकित कर आवश्यक कार्रवाई हेतु समर्पित किया जाता है।

अतः MR (3054) नई अनुरक्षण नीति 2018 (Package No. RM/SI/PUP/19/0001) योजनान्तर्गत अनुरक्षण हेतु अधियाचना प्रपत्र में दर्शाये गये अधियाचित राशि उपलब्ध कराने की कृपा की जाय।

अनु0:-1. अधियाचना प्रपत्र।

2. Signed Hard Copy of recorded IRI is enclosed

3. Standard Format for Roads Quarterly Statement

विश्वासभाजन

19/06/24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, पुपरी।
19/06/24

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Pupri

1 Year (4th Quarter)

Government of Bihar

OM101

Rural works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From-Hari Nagar Nayatola Dadhi Kurhan Raipur

Length of Road: 2.10 KM

Period : From 29.07.2021 To 28.10.2021

Inspector: A.E RWD Sub Division, Nanpur

To: Executive Engineer
RWD Works Division Pupri
Date:
Position: A.E

Standard Work item			Work	Units of work required in each kilometre										Comments
S No	Name	Units	1	2	3	4	5	6	7	8	9	10		
OM100 Sealed Pavement														
OM101	Pothole Patching	m2	Nil	Nil	Nil								No. Pothole found.	
OM102	Surface Depression and Rut Patching	m2	Nil	Nil	Nil								No Surface Depression and Rut Patching found	
OM103	Crack Sealing	Lm	Nil	Nil	Nil								No Crack Sealing found	
Surface Treatment														
OM104	(a) Loss of Aggregate (Surface Ravelling)	m2	Nil	Nil	Nil								No Loss of Aggregate (Surface Ravelling) found	
	(b) Bleeding/Flushing	m2	Nil	Nil	Nil								No Bleeding/Flushing Required	
	(c) Crocodile Cracking	m2	Nil	Nil	Nil								No Crocodile Cracking found	
OM105	Edge Repair	m2	Nil	Nil	Nil								No Edge Repair Required	
OM106	Digouts	m2	N/A	N/A	N/A									
OM107	Concrete Pavement	m3	N/A	N/A	N/A									
Other activities			Lm											
OM200 Shoulder														
Unsealed Shoulder			No											
OM201	(a) Edge Drop off	Lm	Nil	Nil	Nil								No Edge Drop off Required	
	(b) Roughness, Scouring or Potholes	Lm	Nil	Nil	Nil								Defects rectified within stipulated time	
	(c) Holding Water	Lm	Nil	Nil	Nil								No Holding water found	
OM202	Embankment Repair	No	Nil	Nil	Nil								No Embankment Repair Required	
	Other Activitie (Raincut)		2%	1%	2%								Defects rectified within stipulated time	
OM 300 Drainage including culverts major														
OM301	Surface Drains & Verge	Lm	N/A	N/A	N/A								Not Required	
OM302	Culvert Cleaning	Lm											Culvert maintain within stipulated time	
OM303	Culvert and Pit repair	m2	Nil	Nil	Nil								Not Required	

Other activities (White washing)	m ²	Nil	Nil	Nil	Nil														Not Required
OM 400 Vegetation																			
Grass Control																			
OM401 a) Roadside-General Tidy	Ha	Nil	Nil	Nil	Nil														Not Required
b) Clear near Safety signs, kilometer posts and roadside furniture	Ha	Nil	Nil	Nil	Nil														Not Required
Tree and shrub management	No	Nil	Nil	Nil	Nil														Not Required
Cutting trees	No	Nil	Nil	Nil	Nil														Not Required
Cutting Shrubs	No	Nil	Nil	Nil	Nil														Not Required
Other activities (Trimming of Grass)	M ²	Nil	Nil	Nil	Nil														Not Required
OM500 Safety Signage and Road																			Not Required
OM501 Signs Maintenance	No	Nil	Nil	Nil	Nil														Not Required
OM502 Guard Stones	Lm	N/A	N/A	N/A	N/A														Not Applicable
OM503 Distance Stones	No	N/A	N/A	N/A	N/A														Not Applicable
OM504 Road Marking	m ²	Nil	Nil	Nil	Nil														Not Required
Other activities																			

Junior Engineer
Work Section, Nagpur

Assistant Engineer
Work Sub Division, Nagpur

Executive Engineer, Rural Work Department,
Work Division, Nagpur

STANDRAD FORMAT FOR ROADS QUARTERLY STATEMENT (4th Quarter)

1	Name of the Road	Hari Nagar Nayatola Dadhi Kurhan Raipur		
2	Batch No.	RM/SI/PUP/19/0001		
3	Project ID	31607902333		
4	Total Length of Road (in Km)	2.100		
5	Length of Road to Meet Required Service Level [Completed length] (in Km) (1)	2.100		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule (Agreement Amount for Maintenance) (in Lakh)	16.57796		
8	Quarterly Payment :1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) (2)	0.82890		
Compliance Criteria	Standard Job Description	Non-Compliant		Reduction Payment (6) = (3) / (1) * (2) * (4)
		Length Non Compliant (3)	Weighted Value for Payment Reduction (%) (4)	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00000
II	SHOULDERS AND EMBANMENTS	0	10%	0.00000
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00000
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00000
V	VEGATAION		5%	0.00000
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				0.82890

Date of inspection by E/I or his agent Prepared by
Contractor's self Control unit

Date

Signature of person inspecting road

Name and Designation of person inspecting road
(Signature)

Certify by E/I (signature) Date



Name of work		: Hari Nagar Nayatola Dadhi Kurhan Raipur													
Name of customer		: RAJESH KUMAR													
(R)Rural Road															
Good				Average				Poor							
< 4000				4001 - 5000				> 5000							
Date	Time	Test No	Distance(m)	Total Distance(m)	BUMPI(cm)	Speed(Km/Hr)	Ultram(Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
18-04-2024	17:04:58	34	100	100	31.0 cm	3.0 Km/Hr	3100.0 mm/Km	3199	4.27	Good	26.3959701	N	85.8797037	E	Normal
18-04-2024	17:05:40	34	100	200	26.0 cm	6.6 Km/Hr	2600.0 mm/Km	2736	3.71	Good	26.4014254	N	85.8898677	E	Normal
18-04-2024	17:06:01	34	100	300	16.0 cm	17.5 Km/Hr	1600.0 mm/Km	1810	2.57	Good	26.4008017	N	85.8891863	E	Normal
18-04-2024	17:06:18	34	100	400	35.0 cm	19.8 Km/Hr	3500.0 mm/Km	3569	4.7	Good	26.400094	N	85.8895647	E	Normal
18-04-2024	17:06:34	34	100	500	34.0 cm	23.4 Km/Hr	3400.0 mm/Km	3478	4.6	Good	26.399394	N	85.8880748	E	Normal
18-04-2024	17:06:49	34	100	600	19.0 cm	23.1 Km/Hr	1900.0 mm/Km	2088	2.91	Good	26.3985929	N	85.8847467	E	Normal
18-04-2024	17:07:02	34	100	700	24.0 cm	28.2 Km/Hr	2400.0 mm/Km	2550	3.49	Good	26.397788	N	85.8844721	E	Normal
18-04-2024	17:07:16	34	100	800	25.0 cm	25.9 Km/Hr	2500.0 mm/Km	2643	3.6	Good	26.3969526	N	85.8840743	E	Normal
18-04-2024	17:07:31	34	100	900	29.0 cm	23.8 Km/Hr	2900.0 mm/Km	3014	4.04	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:07:46	34	100	1000	28.0 cm	23.9 Km/Hr	2800.0 mm/Km	2821	3.93	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:08:00	34	100	1100	19.0 cm	27.0 Km/Hr	1900.0 mm/Km	2088	2.51	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:08:13	34	100	1200	30.0 cm	27.2 Km/Hr	3000.0 mm/Km	3106	4.16	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:08:27	34	100	1300	20.0 cm	26.2 Km/Hr	2000.0 mm/Km	2180	3.03	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:08:41	34	100	1400	29.0 cm	25.7 Km/Hr	2900.0 mm/Km	3014	4.04	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:08:54	34	100	1500	32.0 cm	27.0 Km/Hr	3200.0 mm/Km	3291	4.58	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:09:08	34	100	1600	26.0 cm	23.6 Km/Hr	2600.0 mm/Km	2736	3.71	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:09:28	34	100	1700	19.0 cm	19.4 Km/Hr	1900.0 mm/Km	2088	2.91	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:09:48	34	100	1800	21.0 cm	21.6 Km/Hr	2100.0 mm/Km	2273	3.14	Good	26.3969505	N	85.8839405	E	Normal
18-04-2024	17:10:57	34	100	1900	24.0 cm	16.6 Km/Hr	2400.0 mm/Km	2850	3.49	Good	26.3969505	N	85.8839405	E	Normal

Km
19/04/24

Sumit
19/04/24

19/04/24


Name of work		Hari Nagar Nayatola Dadhi Kurhan Raipur													
Name of customer		RAJESH KUMAR													
		(R) Rural Road													
		Good	Average				Poor								
		< 4000	4001 - 5000				> 5000								
18-04-2024	17-10-24	34	100	2000	36.0 cm	20.9 Km/Hr	3600.0 mm/Km	3662	4.81	Good	26.3960505	N	85.6836405	E	Normal
18-04-2024	17-10-44	34	100	2100	24.0 cm	18.7 Km/Hr	2400.0 mm/Km	2550	3.49	Good	26.3868246	N	85.6802225	E	Normal

For
19/6/24

For
19/11/24
He

For
19/06/24

Name of Customer: RAJESH KUMAR, Machine no: 19199, Road: Hari Nagar Naratola Dadhi Kurhan Raipur, Date: 18-04-24, Section No: 34, Equation: $Y=0.926X-328.1$



for
19/6/24

Rajesh
19/6/24
etc

for
19/6/24