

MMGSY, Tcy to Pachaukhia
GEN

Ag. No: 32500/19-20 (Ag. Val. 100.71110)

Schedule XLV-Form No. 134

Shinglafi DIVISION

Galunna SUB-DIVISION

Agency: Stifal Pvt. Constn Pvt. Ltd.

MEASUREMENT BOOK

MB no-1126

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	300 Yers Maindine Hill.				
N/w -	Maintenance of road				
	from To 7 to pachrutehize.				
	under Luma Block.				
Agency -	Sital Prasad Construction				
	Private Limited - (Chaya.)				
Agreement No -	32 S.N. 2019, 20				
Date of work -	28.9.2020				
Date of completion	27.07.2020				
Actual date of completion	12.6.2021				
below -	10%				
Date of entry -					
	Borrow with soil				
	Modern - do do				
	$2 \times 30 \times 1.20 \times 0.30 =$				
	$2 \times 15 \times 1.10 \times 0.30 = 21.6 \text{ m}^3$				
	$2 \times 20 \times 1.00 \times 0.30 = 12 \text{ m}^3$				
	$2 \times 10 \times 1.20 \times 0.30 = 7.2 \text{ m}^3$				
	$2 \times 30 \times 1.00 \times 0.30 = 18 \text{ m}^3$				
	$2 \times 19 \times 1.20 \times 0.30 = 13.68 \text{ m}^3$				
	$4 \times 30 \times 1.00 \times 0.30 = 36 \text{ m}^3$				
	$T = 108.48 \text{ m}^3$				
(2/15.12.20)	Making up of borrow.				
	shoulder stripping				
	excess soil from				
	the shoulder do				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
12 15.13					White washing of parapet, wall of CD tank etc.
					$2 \times 2 \times 6.5 \times 1.80 = 44.64m^2$
					$1 \times 2 \times 3.60 \times 1.80 = 12.96m^2$
					$2 \times 2 \times 6.10 \times 1.80 = 43.20m^2$
					$\frac{100.80m^2}{108.80m^2}$
					limit 105.00m
17.5.2024 OE.					17.5.2024

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Abstract of cart
15.1					Restoration of minute
					Brooms with soil/mowing
					chuck - Qty vide
					Item no. 68 item no. 1
					108.48 m ³ @ 380.58/m ³ H ₂ 41285/-
2 15.201					Making up of brooms,
					shoulders - chucks
					Qty vide Item no. 68, 69
					item no. 2
					602.4 m ² @ 58.37/m ² H ₂ 35162/-
3 15.5					Repair of pot holes
					Qty vide Item no. 67
					item no. 3
					0.32 m ³ @ 10255.14/m ³ H ₂ 3282/-
4 15.3.11					patch repair over
					Bituminous surface with
					20 mm thickness chills
					Qty vide Item no. 69
					item no. 4
					106.27 m ² @ 280.06/m ² H ₂ 29762/-
5 15.7.10					Maintenance of CD
					work done vide
					Qty vide Item no. 70
					item no. 5
					0.3 m ³ @ 1117.1/cu m H ₂ 3351/-
					Continuation 112842/-

73
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(A) 157.11'			B ¹ B ₅ =		
Maintenance of CD					
work slab cement choko					
Qty side Twp. p. 70					
Item no 6					
0.2 Nos @ 2309.03/Echpts 4618 =					
(7) 15.9.			Maintenance of road		
bridge choko					
Qty side Twp. p. 70					
Item no 7					
0.25 km @ 1074.51/km ts = 2692					
(8) 15.11			Maintenance of road		
Qty side Twp. p. 70					
Item no 8					
0.30 km @ 657.71/km ts = 1972					
(9) 15.120			Cutting of branches of trees choko		
Qty side Twp. p. 70					
Item no 9					
10 Nos @ 106.52 Echpts 10652					
(10) 15.120			Cutting of surplus from land nearby choko		
Qty side Twp. p. 70					
Item no 10					
776 m ² @ 2.18/m ² ts = 1692 =					
1531 Nos @ 6.54/Echpts 10013 =					

Continuation Tc 1290042

