

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work - Jagdish Pakri chowk to chapar gram na Jagdish Sah ke ehar					
② Agang Sanjeev kumar Prp. Pakrat Rai					
③ Ag No - 1111884/SM - 73/18-19					
④ Actual date of completion - 12-06-2019					
⑤ Restoration of pavement					
464 4.15 x 0.90 x 0.60 = 103.09 m ²					
19 x 3.25 x 0.95 x 0.55 = 32.26 m ²					
Unit -					134.87 m ²
⑥ maintenance of earthen shoulder					
27 x 2.50 x 0.90 = 72.80 m ²					
1 x 2.4 x 0.85 = 20.4 m ²					
					749.4 m ²
Unit -					749.25 m ²
⑦ Repair to pot-holes.					
2 x 5.65 x 2.90 = 147.16 m ²					
1 x 9.35 x 3.75 = 35.06 "					
1 x 8.60 x 2.85 = 23.94 "					
1 x 9.60 x 3.45 = 33.12 "					
1 x 8.95 x 3.35 = 29.98 "					
1 x 9.7 x 3.65 = 35.40 "					
					173.88

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of sawn cul					
	Trans P(63)	134.87m			
	@ 365	40/m			- 649,281 ~
2. Maintenance of earthen channel					
	Trans P(63)	749.25m			
	@ 54	39/m			- 40,752 ~
3. Repairs to Dist cul					
	Trans P	173.44m			
	@ 507	83/m			- 36,046 ~
4. Paving of sub-drain					
	Trans P(63)	360.00m			
	@ 770	48/m			- 2,77,373 ~

5. Patch repairs					
	Trans P(63)	210.88m			
	@ 263	40/m			- 249,852 ~
6. Maintenance of H.P. cul					
	Trans P(63)	2.0			
	@ 1132	27/m			- 2265 ~
7. Maintenance of slab type cul					
	Trans P(63)	8.04			
	@ 2338	26/m			- 18,704 ~
8. Maintenance of concrete & kerbs					
	Trans P(63)	18.5m			
	@ 728	76/m			- 13,120 ~
					54,75,585 ~

Calculated
26/06/24
JE/12/12/24