

2nd year maintenance

32

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Maintenance of Road from					
S100 Bavan ghat Mukher hole					
to machi tola pul take.					
Agency.	Samir Alam				
Agri. No.	45 (S.B.D) / 2021-22				
D.O. W.	03.07.2021				
Actual D.O.C.	26.06.2022				
① Rotation of Rainauts -					
L.H.S	{	5 x	3.25 x	0.80 x 0.35 =	4.55
		9 x	2.45 x	0.75 x 0.30 =	4.96
R.H.S		4 x	3.00 x	0.90 x 0.30 =	3.24
L.H.S		10 x	2.50 x	0.85 x 0.35 =	7.44
R.H.S		12 x	2.65 x	0.90 x 0.30 =	8.58
L.H.S		8 x	3.15 x	0.85 x 0.35 =	7.50
					36.27 m ³
② Maintenance of Earthen					
Shoulder					
R.H.S	{	6 x	8.00 x	0.85 =	40.80
		10 x	7.50 x	0.80 =	60.00
L.H.S	{	12 x	6.00 x	0.75 =	54.00
		11 x	5.00 x	0.90 =	49.50
					204.30 m ²
③ Maintenance of Road Sign -					
0.550 km					
④ Paint. of 200 m of km stone -					

12/06/29
JL

material

ඉ/ක. 61.25 ම³

12/06/29
IS