

2nd year maintenance

Name of work— **1**
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
No. of L.S.S. Bhanpur Madwar Ashan to Baga Bela to Bawan ghad hvd talc.					
Agr. No Agency - 23(C&B D)/2021-22					
Agency Agr. No. - Rajiv Kumar Jho.					
D.O.W -					
D.O.C -					
Actual D.O.C -	06.05.2022				
Date of entry.					

① Restoration of Barbed

R.H.S	8 x 2.75 x 0.90 x 0.35 =	6.93
	12 x 2.80 x 0.90 x 0.30 =	9.07
	14 x 2.65 x 0.95 x 0.30 =	10.57
	11 x 2.50 x 1.00 x 0.35 =	9.62
	10 x 3.10 x 0.85 x 0.30 =	7.90
	15 x 2.70 x 0.95 x 0.30 =	11.54
		58.63 m ²

② Maintenance of earthen

L.H.S	Shoulder —	36.00
	5 x 8.00 x 0.90 =	36.00
	9 x 5.00 x 0.85 =	38.25
	12 x 6.00 x 0.95 =	68.40

