

3rd year maintenance

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

1/21. Maint. of Road from 1040
to Hampur Alloth Pachimi
tola. under HHM (sc).

Agency - Raymoni

Agri. No. 58 S.D. (2020-21)

D.O.W. 08.09.2020

D.O.C. 03.06.2021

Actual D.O.C.

Date of Entry - 21-05-2021

Details -

① Restoration of Corners -

R.H.S. $\left\{ \begin{array}{l} 6 \times 2.95 \times 1.10 \times 0.35 = 6.81 \\ 8 \times 3.25 \times 1.00 \times 0.30 = 7.80 \end{array} \right.$

L.H.S. $\left\{ \begin{array}{l} 5 \times 3.15 \times 1.15 \times 0.30 = 5.43 \\ 4 \times 3.40 \times 1.25 \times 0.35 = 5.95 \\ 7 \times 3.00 \times 1.20 \times 0.35 = 8.82 \end{array} \right.$

34.81 m³

② Making up of Berms/
Shoulder -

R.H.S. $\left\{ \begin{array}{l} 7 \times 4.00 \times 0.85 = 23.80 \\ 9 \times 7.50 \times 0.90 = 60.75 \end{array} \right.$

L.H.S. $\left\{ \begin{array}{l} 10 \times 6.00 \times 0.95 = 57.00 \\ 8 \times 5.50 \times 0.80 = 35.20 \end{array} \right.$

R.H.S. $\left\{ \begin{array}{l} 5 \times 3.50 \times 0.95 = 16.62 \\ 6 \times 6.25 \times 0.85 = 31.87 \end{array} \right.$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
20.64 m ² @ R. 97.19/m ² R. 2006 =					
(7) Road marking					
(i) BT Surface					
84 wide THB-R-34					
90.10 m ² @ R. 735.44/m ² R. 66190 =					
(ii) C.C. portion					
84 wide THB-R-34					
50.10 m ² @ R. 735.44/m ² R. 36772 =					
(8) Mark. of plant					
84 wide THB-R-35					
50.10 m ² @ R. 574.00/m ² R. 17220 =					
					R. 167332 =
					/

					R. 167332 =
Acyl Inst + L. (134)	(4)				R. 2753 =
Acyl s. Fee					R. 355 =
					R. 189440 =
Low Below (11.23.1.2)	(1)				R. 21464 =
					R. 167976 =

Bow
 21/05/24
 J-8