

1st year Maintenance bill.

Particulars		Details of actual measurement				Contents of area
No.	L.	B.	D.			
N/N:- Maintenance of Road from						
MNP Sadak Tumraul to Tumraul						
Dakshinwadi side.						
Agency: Sri Sanjay Kumar Jha.						
Agg No:- 48/SB/2018-19 MNGS (SC)						
Agg Rate:- 10/- Below.						
D.O.S:- 09-03-2019						
D.O.C:- 09-02-2020						
Recorded on:-						
① Restoration of Rain						
Cent - - - - - 41,						
9 Nos	2.90m	0.90m	0.3m	=	7.047 m ³	
15 Nos	2.40m	1.00m	0.30m	=	10.80 m ³	
26 Nos	2.70m	0.95m	0.3m	=	20.007 m ³	
10 Nos	4.50m	0.80m	0.3m	=	10.80 m ³	
14 Nos	3.80m	0.75m	0.3m	=	11.97 m ³	
					60.624 m ³	
② Making up of Berms/						
Shoulders - - - - - 41,						
8 Nos	20.00	0.80m		=	12.80 m ²	
15 Nos	12.00	0.9m		=	162.0 m ²	
4 Nos	9.00	1.00		=	36.0 m ²	
					326.0 m ²	
③ Maintenance of						
Work of road. 2.0 Nos.						
④ (i) cutting of branch						
of trees - - - - - 41 2.0 Nos.						

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(42) cutting of Shauls from Road way.					8.0 Nos.
(5) White washing on parapet wall.					
	2 Nos	4.00	3.85	1.10	= 30.80 m ²
	2 Nos	4.00	0.40	0.50	= 1.60 m ²
	2 Nos	2.00	3.85	0.40	= 6.16 m ²
	2 Nos	2.00	3.85	0.60	= 9.24 m ²
					47.80 m ²
16 18-02-21					

Abstract of cost.					
(VI) Restoration of Rain					
Cut - - - - -					
(60.624 m ²)	Qty in dep	(37) TmB			
59.24 m ²	CR 390.29/m ²		R	23315 =	
(212)	Making up of Bricks				
	shw. ideas - - -				
376.0 m ²	Qty in dep	(37) TmB			
	CR 52.17/m ²		R	17007 =	
(377)	Main drainage of CD				
	Work H/Culvert.				
2.0 Nos	Qty in dep	(37) TmB			
	CR 1131.64/each		R	2268 =	
(411)	cutting of braced beams				
2.0 Nos	Qty in dep	(37) TmB			
	CR 118.23/each		R	236 =	
Continuation				R 42821 =	
C.S					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F	R	42821 = ∞
(22) cutting & shoulders					
from Road way -					
8.0 mrs Hyridep (38) tons					
CR 6.60/each				R	53 = ∞
(5/12) White washing on					
parapet walls.					
47.80 mrs Hyridep (38) tons					
CR 15.98/each				R	764 = ∞
				R	43638 = ∞
Less 10% as per AJOH				R	4364 = ∞
				R	39,224 = ∞

2019 year maintenance

41

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Maintenance of Road from					
MNP Sadak Tumau to					
Tumau Dakhshin dvari					
Jula.					
Agency:- Smt. Sanyam Kumar Sta.					
Job No:- 4A/500/111/214 (SC)					
Job Rate:- 101.15 per sq. m.					
D.O.S:- 09-03-2019					
D.O.C:- 09-03-2020					
Recorded on:-					
① Restoration of Rain					
Cust. --- a ₁					
18 Nos 4.30 x 0.250 x 0.30 = 17.415 m ²					
25 Nos 2.70 x 0.90 x 0.30 = 18.225 m ²					
22 Nos 2.90 x 1.00 x 0.30 = 19.14 m ²					
9 Nos 3.50 x 0.95 x 0.30 = 8.925 m ²					
10 Nos 2.50 x 0.90 x 0.30 = 6.75 m ²					
					70.508 m ²
② Making up of Besoms					
Shoulder --- a ₂					
16 Nos 15.00 x 0.85 = 204.00 m ²					
9 Nos 10.00 x 1.00 = 90.00 m ²					
8 Nos 9.00 x 1.00 = 72.00 m ²					
10 Nos 3.00 x 0.90 = 27.00 m ²					
					393.00 m ²
③ Maintenance of					
Work by Contract - 2.00 Nos.					

Continuation

C-9



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(17) Maintenance of Road signs - - - - -	al,				1.180 km
(18) Maintenance of 200M Stone - - - - -	u,				1.180 km
(19) cutting of branches of trees - - - - -	ch				2.000 d
(20) cutting of shrubs from Road way - - - - -	ce,				8.000 d.
 At 04.03.22 for At 04.03.22 for 					

Abstract of work					
(11) Restoration of Rain out - - - - -	u,				
70.508 m ³ at bridge (41) TMB					
CR 390.29 / m ³ - - - - -					27519 =
(12) making up of Berms / shoulders - - - - -	ce,				
393.00 m ³ at bridge (41) TMB					
CR 52.17 / m ³ - - - - -					20503 =
(21) Maintenance of Road signs - - - - -	al,				
1.18 km at bridge (42) TMB					
CR 1055.94 / km - - - - -					1246 =
(12) making up of Berms / shoulders - - - - -	ce,				
2.004 m ³ at bridge (41) TMB					
CR 1131.64 / each - - - - -					2263 =

Continuation

C.O

51531 =

Scanned with OKEN Scanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Measure of area. Main line of road from					
MNP Sadak to road to road					
Dakshinwari to la.					
Agency. Sanjay Kumar Jha.					
Agmt 48/15/2019/2018-19					
Dakshinwari. 09/03/2019					
Dakshinwari. 08/03/2020					
Refused 9/2/2022					
32 yd 9/2/2023					
Main line of road					
(1) Rest of area of road on					
area of road					
	18x	5.00x	0.90x	0.30	24.20m ²
	15x	3.00x	1.00x	0.30	13.50m ²
	18x	4.00x	1.10x	0.30	22.76
	5x	6.00x	1.00x	0.30	9.00
	15x	3.00x	1.00x	0.30	13.50
					84.66
					83.63m ²
(2) Measure of area of road on					
do do do do do					
	10x	11.00x	0.90	2	99.00m ²
	15x	12.00	1.00	2	180.00m ²
	12x	11.00x	0.80	2	105.60
	2x	5.00x	1.20	2	12.00
					396.60

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Refuse collection					
area - - - - -					
wide T.M. R.R. (44) 21 (1)					
83.63 M ² @ R. 390.29/-					R. 3264020
(2) Making up of drains/sheds					
do - - - - -					
wide T.M. R.R. (49) 21 (2)					
396.60 M ² @ R. 52.12/-					R. 2069120
(3) Repair of pot hole drain					
area R.R. - - - - -					
wide T.M. R.R. (45) 21 (3)					
4.22 M ² @ R. 10855.96/-					R. 458120
(4) patch repair					
R.R. pot hole - - - - -					
wide T.M. R.R. (45) 21 (4)					
56.23 M ² @ R. 226.25/-					R. 127270
(5) Main low of CD/H.R.					
do - - - - -					
wide T.M. R.R. (43) 21 (5)					
4 Nos. @ R. 1131.64/-					R. 452720
(6) Vehicle washing shed					
area - - - - -					
wide T.M. R.R. (43) 21 (6)					
84.00 M ² @ R. 15.98/-					R. 13420
					R. 1177390
Less 10% below					R. 117740
					R. 1059650
Material					

Continuation

Scanned with OKEN Scanner

Continuation

Scanned with OKEN Scanner