

4th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Restoration of Roadcut					
N/w: Maint. of Road from 1085					
14thmiden hole to Kurmsi hole under					
M.H.Sy maintenance.					
Agency- Sri. Prayash Kumar					
Aggr. No. 19(S35)/2018-19					
D.O.W- 04.05.2018					
D.O.C- 03.11.2018					
Actual date of Comp- 19.03.19					
Date of entry - 21-03-2023					
① Restoration of Roadcut -					
R.W.S	3	2.15	1.03	0.35	2.16
	6	4.10	0.95	0.30	6.84
L.S.S	10	3.10	1.10	0.30	9.9
	12	2.50	0.90	0.30	8.10
L.S.S	15	2.75	1.00	0.35	14.43
	04	8.50	1.20	0.35	5.88
					<u>20.48</u>
					47.31 m ²
② Maintenance of Earthen shoulder					
R.W.S	4	6.00	0.90		21.60
	6	5.50	0.95		31.35
	10	5.0	0.90		45.00
L.S.S	8	7.00	0.85		47.60
	12	4.00	0.95		45.60
	10	10.00	0.90		90.00
					<u>281.15 m²</u>

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(A) Maint. of Road sign -					
Qty with TMB P-36					
0.54 km @ R. 1067.44/km - R. 576 =					
(C) Maint. of 200 m-p km stone -					
Qty with TMB P-36					
0.10 km @ R. 675.29/km - R. 68 =					
(G) Cutting of branches -					
Qty with TMB P-36					
3.60 km @ R. 104.48/km - R. 313 =					
(F) Trimming of Grass -					
Qty with TMB P-36					
1.455.63 m ² @ R. 2.14/m ² - R. 975 =					
					R. 32957 =

Less 10% Below	R. 32957 =
	R. 29656 =

21/03.23
58

Material

Q/wr 80.19 m³

21/03.23
58