

5th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Maint. of Road from Rebra to Jagdishpur.					
Agency- Sri. Krishna Kumar Jha.					
Ag. No- 11 CB/2017/2017-18					
D.O.W- 04.07.17					
D.O.C- 03.01.18					
Actual D.O.C- 05.08.18					

Details

① Rectification of Raincut

L.H.S	4x	3.40x	1.25x	0.35=	5.25
	10x	3.25x	1.10x	0.30=	10.72
R.H.S	12x	2.90x	0.95x	0.30=	9.92
	8x	2.50x	1.10x	0.35=	9.10

L.H.S	11x	2.25x	1.15x	0.30=	8.54
	15x	2.40x	0.90x	0.35=	11.34
R.H.S	8x	2.75x	0.95x	0.30=	6.27
	12x	3.00x	0.90x	0.35=	11.34

70.38 m²

② Maintenance of concrete shoulders

L.H.S	10x	7.00x	1.10		77.00
	12x	6.50x	0.95		74.10
	10x	5.00x	1.10		55.00
R.H.S	9x	8.00x	0.90		64.80
	10x	4.00x	1.10		44.00
	11x	5.50x	1.25		75.62

385.52 m²

Male -
Q/wr. 1 13.60 m²
15/08/23
28

1		
Q _{year}	113.60	m ³

15/08/23
32