

5th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/w: Maintenance of Road from
L-88 Panchrukhi to Chhoti busar.

Agency - Bamborn kumar.

Agri. No - 59 (SBD) / 2017-18

D.O.W - 19.01.2018

D.O.C - 18.10.18

Actual date of Completion - 15.10.2018

Date of measurement - 15/10/2023.

Details

① Restoration of Rainfall

R.H.S	6	1.80	0.95	0.30	3.07
	10	2.15	0.90	0.35	6.77
	9	1.75	0.90	0.30	4.25

L.H.S	5	3.10	0.85	0.35	4.61
	12	2.45	0.80	0.35	8.23
	7	2.80	0.90	0.30	5.29

R.H.S	4	3.25	0.85	0.30	3.31
-------	---	------	------	------	------

L.H.S	15	2.90	0.95	0.30	12.39
	10	2.85	0.90	0.30	7.69

R.H.S	14	2.78	0.90	0.30	10.39
	12	2.40	0.85	0.30	7.34

73.34 m²

② Maintenance of earthen
shoulder

L.H.S	15	30.00	0.85	382.50
-------	----	-------	------	--------

R.H.S	12	25.00	0.80	240.00
-------	----	-------	------	--------

622.50 m²

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5. work @ R. 102.49/each					R. 51220
(C) Trimming of ground					
Qty like this 1-40					
1123.00 m ² @ R. 240/m ²					R. 236320
					R. 546460
less 10% Belong					R. 546500
					R. 4918100
1510-20					
Material					
Qty. 137.12 m ³					
1510-20					