

**कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, रजौली।**

Mob No.: 8986915851.

Email I.D.: - eerwdrajauli@gmail.com

पत्रांक... २७६ अनु०...

रजौली / दिनांक... १२/०३/२४

प्रेषक,

ई० अरविन्द कुमार,
कार्यपालक अभियंता।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण, पटना।


विषय :- नई अनुरक्षण नीति-2018 योजनान्तर्गत आवंटित राशि का उपयोगिता प्रमाण पत्र तथा आवंटन अध्याचना के संबंध में।

महाशय,


उपर्युक्त विषय के संबंध में कहना है, कि इस प्रमंडल के अधीन नई अनुरक्षण नीति-2018 योजनान्तर्गत पथों में चल रहे कार्य के भुगतान हेतु विहित प्रपत्र में माँग पत्र एवं उपयोगिता प्रमाण पत्र संलग्न करते हुए आग्रह है, कि आवंटन उपलब्ध कराने की कृपा की जाय ताकि कराये गए कार्यों का भुगतान किया जा सके।

अनु० :- यथोक्त।

विश्वासभाजन,



कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, रजौली।


12/03/24

Requisition for Scheme Head :- MR (3054) under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Works Division: RWD (W) Division, Rajauli

Sl. No	Package No-	Name Of Road	Project Id as per MIS	Administrative Approval (AA) Letter No- & Date	Administrative Approval (AA)		Agreement Amount		Agreement No- & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen content in percentage	Previous Total allotted Amount (in Lakh)	upto date expenditure as per MIS (in Lakh)	Requisition against work done (in lakh)	Remarks
					Length (in km)	Amount (in lakh)	Initial Rectification with surface Renewal (in lakh)	5 years routine Maintenance (in Lakh)										
01	RM/NA/RAJ/23/009	Kusahan SH -70 To Bharsanda Via Pipra	15271037242	Lt. 118/ 08.03.22	2.090	84.21000	53.56470	16.80460	02/MBD/ MR-3054/2022-23	11-01-2024	-	2945	25	5.00	0.00000	0.00000	48.20823	Going
02	RM/NA/RAJ/23/0013	SONWAY TO CHAUBEY (Reciend work)	10502702222	Lt. 1942/ 28.03.23	2.492	144.18000	97.89318	21.55810	11 MR-3054/MBD/ 2023-24	11-07-2024	-	2635	25	5.00	0.00000	0.00000	88.10386	Going
3	RM/NA/RAJ/23/009	Construction of Road from Tekhahi More to Henja Bharat in Dhiroundh Gram Panchayat	10502701024	Lt. 118/ 08.03.22	3.190	113.94000	70.87215	28.62550	01/MR-3054/MBD/2022-23	17-07-2023	-	3209	25	5.01	44.64945	44.64945	24.18025	Completed
4	RM/NA/RAJ/23/009	Rajauli Sirdala Road (Near Kattha Factory) to Abdul Village	15271034356	Lt. 118/ 08.03.22	1.220	63.26000	44.10820	11.10360	06/MBD/M R-3054/2023-24	16-02-2024	-	2742	25	5.00	27.78816	27.78816	15.71999	Completed
5	RM/NA/RAJ/23/009	Hathmarwa to Bholakurtha Mor	15271034358	Lt. 118/ 08.03.22	3.100	167.43000	116.58654	27.80980	06/MBD/M R-3054/2023-24	16-02-2024	-	2425	25	5.00	104.92788	104.92788	10.45723	Completed
					12.092	573.02000	383.02477	105.90160	0.000	-	-	-	-	-	177.36549	177.36549	186.66956	

In Word One Crore Eighty Six Lakh Sixty Six Thousand Nine Hundred Fifty Six only)

Executive Engineer,
Rural Works Department,
Works Division- Rajauli.

FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150)
Form of Utilization Certificate up to the Month of **12-MARCH-2024**.

S. No	Name of Scheme	Sanction No. & Date with Amount (In Rs.lacs)	Amount Received (in Rs.Lacs)	Decrease (in Lacs)	Particulars
1	Bihar Rural Roads New Maint. Policy 2018	As on 25-MARCH-2023	3787.76798	137.05028	Certified that out of Rs. 6979.91749 Lakh received during the Financial Year 2023-24 (12-MARCH-24) in favour of Executive Engineer, RWD (W) Division, Rajauli, Bihar out of which a sum of Rs. 6117.19652 Lakh has been utilized for the purpose of New Maintenance Policy 2018 Under MR3054 Scheme as given in the margin for which it was sanctioned and Rs. 207.13771 has been surrendered and that the balance of Rs. 655.58326 Lacs remaining unutilized at the end of the said period.
2		Lt. 63 Dt 13.04.23	20.97956	22.11023	
3		Lt. 31 Dt 31.05.23	89.44542	36.56126	
4		Lt. 78 Dt 24.05.23	198.63594	11.41594	
5		Lt. 84 Dt 08.06.23	126.74006		
6		Lt. 85 Dt 14.06.23	129.82321		
7		Lt. 92 Dt 28.06.23	613.59155		
8		Lt. 100 Dt 14.07.23	126.21474		
9		Lt. 113 Dt 14.08.23	247.90635		
10		Lt. 117 Dt 28.08.23	24.11419		
11		Lt. 120 Dt 04.09.23	46.69588		
12		Lt. 129 Dt 27.09.23	131.84459		
13		Lt. 136 Dt 10.10.23	101.11183		
14		Lt. 147 Dt 07.11.23	83.40053		
15		Lt. 151 Dt 10.11.23	144.37968		
16		Lt. 155 Dt 21.11.23	104.92788		
		Lt. 159 Dt 29.11.23	37.50471		
		Lt. 14 Dt 06.02.24	317.96752		
		Lt. 31 Dt 09.03.24	646.86587		
			6979.91749	207.13771	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineers/Superintending Engineer.
- Periodic inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road Works
- Construction of CD Works


 Executive Engineer,
 Rural Works Department,
 Works Division, Rajauli.


 12/03/24


Name of Road - Construction of Road from Tekhahi More to Hemja Bharat in Dhirounth Gram Pachayat													
Batch No- KM/NA/RAJ/23/0009													
Name of Contractor-Sujay Bhan Singh													
Date	Time	Section	Length	Bumps	Speed	OR	Category	IRI	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 0.854 * X + 376.5	
		No	in km	in mm	mm/Km	U/V	ROAD						
13/12/23	10:15:31	33	0.1	280	10.1	2800	2767 G	3.74	24.64746	85.43833	Normal	X = 4149	
13/12/23	10:16:09	33	0.1	310	10.1	3100	3023 G	4.05	24.64661	85.4379	Normal	Y = 3919	
13/12/23	10:16:15	33	0.1	360	20.2	3600	3450 G	4.56	24.6458	85.43751	Normal		
13/12/23	10:16:44	33	0.1	450	20.2	2500	3219 G	5.45	24.64497	85.43719	Speed Breaker		
13/12/23	10:17:00	33	0.1	370	30.3	3700	3536 G	4.66	24.64409	85.43689	Normal	(R) RURAL ROAD	
13/12/23	10:17:19	33	0.1	300	10.1	3000	2938 G	3.95	24.64315	85.43658	Normal	Good	Average
13/12/23	10:17:55	33	0.1	370	10.1	3700	3536 G	4.66	24.6424	85.43626	Speed Break	<4000	4001-5000
13/12/23	10:18:30	33	0.1	270	10.1	2700	2682 G	3.64	24.64161	85.43579	Normal		Poor
13/12/23	10:19:04	33	0.1	470	20.2	3700	3390 G	5.65	24.6407	85.43557	Normal		
13/12/23	10:19:12	33	0.1	370	10.1	3700	3536 G	4.66	24.63992	85.43603	Normal		
13/12/23	10:19:39	33	0.1	310	30.3	3100	3023 G	4.05	24.63914	85.43648	Normal		
13/12/23	10:19:41	33	0.1	350	30.3	3500	3365 G	4.46	24.63833	85.4369	Curve		
13/12/23	10:20:00	33	0.1	290	20.2	2900	2853 G	3.85	24.63743	85.43714	Normal		
13/12/23	10:20:15	33	0.1	250	30.3	2500	2511 G	3.43	24.63658	85.43702	Normal		
13/12/23	10:20:20	33	0.1	340	30.3	3400	3280 G	4.36	24.63573	85.4366	Normal		
13/12/23	10:20:50	33	0.1	450	10.1	3500	3219 G	5.45	24.63506	85.43599	Speed Breaker		
13/12/23	10:21:00	33	0.1	470	10.1	3700	3390 G	5.65	24.63425	85.43584	Curve		
13/12/23	10:21:25	33	0.1	460	10.1	3600	3304 G	5.55	24.63336	85.43616	Speed Breaker		
13/12/23	10:22:01	33	0.1	400	10.1	4000	3792 G	4.96	24.6326	85.4365	Normal		
13/12/23	10:22:36	33	0.1	320	30.3	3200	3109 G	4.15	24.63167	85.4366	Normal		
13/12/23	10:22:40	33	0.1	310	30.3	3100	3023 G	4.05	24.63072	85.43648	Normal		
13/12/23	10:23:00	33	0.1	320	10.1	3200	3109 G	4.15	24.62982	85.43631	Normal		
13/12/23	10:23:11	33	0.1	410	10.1	4100	3877 G	5.06	24.62898	85.43601	Normal		
13/12/23	10:24:00	33	0.1	460	10.1	4600	3304 G	5.55	24.62828	85.43544	Speed Breaker		
13/12/23	10:24:22	33	0.1	270	20.2	2700	2682 G	3.64	24.62824	85.43453	Normal		
13/12/23	10:24:25	33	0.1	350	10.1	3500	3365 G	4.46	24.62852	85.4336	Normal		
13/12/23	10:25:00	33	0.1	280	20.2	2800	2767 G	3.74	24.62869	85.43263	Normal		
13/12/23	10:25:12	33	0.1	380	30.3	3800	3621 G	4.76	24.62889	85.43167	Curve		
13/12/23	10:26:08	33	0.1	520	20.3	2200	3817 G	6.14	24.62817	85.43128	Speed Breaker		
13/12/23	10:26:10	33	0.1	340	20.2	3400	3280 G	4.36	24.62788	85.43044	Curve		
13/12/23	10:26:15	33	0.1	320	20.2	3200	3109 G	4.15	24.62758	85.42949	Curve		
13/12/23	10:26:43	33	0.090	230	20.2	2840	2801 G	3.78	24.62761	85.42859	Normal		
Total		3.190	11380.00	585.90	105340.00	102678.00							
Average			355.63	18.31	3291.88	3208.69							

13/12/23

13/12/23

14-12-23

File: E:\Manish\Maintenance Bump Data of Rajauli\Suray Bhan Singh\Construction of Road from Tekhahi More to
 Name of Customer: Suray Bhan Singh. Name of Work/ Road: Construction of Road Tekhahi More to Hemja Bharat in



[Signature]
 13/12/2023

[Signature]
 13/12/2023

[Signature]
 14-12-2023
 EE

Saxdala Thakali More to Hemza in

Dharanadi Uxam Panchayat

M. R

Shedule XLV Form No. 134.

Susay Bhan Singh.

DIVISION

SUB-DIVISION

पराम

Measurement Book

M. G. No - 1299

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work Construction of road m/R 3054 Sindole Tekhari Mor to Hapur in Dhund gram Panchayat					
Name of Agency:- S. Gajraj Bhargava Mawada					
Agreement No Regular or mss/ml 1012-23 -3054					
Date of Commencement 12/4/2023					
1/13 Prind & fix of Reto. Reflexing information Sign Board of 60cm equilateral Triangular 10 11 is					
2/14 Prind & fix of retroreflective Sign Board of 60cm x circular Board 4 is					
3/15 Prind & fix of retroreflective Sign Board of 60cm x 450 size 100 8 is					
4/16 Prind & fix of Body of R.M.V. 7 is					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5/17. Planting of Trees and their maintenance.					
		1			82 m
6/2 Construction of subgrade and extra shoulder with approved mix.					
... all Comp. job m/c					
	2x	21x30.0x	1.07x	0.3m	378.0 m ³
	2x	16x30.0x	0.9x	0.25m	216.0 m ³
	2x	27x30.0x	1.1x	0.3m	534.6 m ³
	2x	10x30.0x	0.9x	0.2m	108.0 m ³
	2x	29x30.0x	1.1x	0.3m	574.2 m ³
					180
					1210.8 m ³

15/12/24
OE

16/2/24
AC

Seymour's Calculator

① E/m - 1810.2 m³ 61567
 61547
 180
 61547

Hence Seymour's

10% of total m³ 61557

15/12/24
OE

16/2/24
AC

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
<u>ABSTRACT OF COST</u>				
1/1	clearing & grubbing and land			
0.64	1400	side	ton, 1/4	
		CR 52716 13/14 38.15		
2/3	Granular Sub Base with well graded			
128.333	3	side	ton, 1/4	
		CR 12402 31/2 2,19,057		
3/4	Worn. Gravel - 2 Prindf layer 1/2			
114.35	3	side	ton, 1/4	
		CR 3187-86 1/3 3,64,532		
4/5	Worn Gravel - 3 Prindf layer 1/2			
250.012	3	side	ton, 1/4	
		CR 2955-81 1/3 7,38,982		
5/6	Prime Coat - Prindf and apply 1/2			
3333.47	3	side	ton, 1/4	
		CR 59-51 1/2 1,98,375		
6/8	Tack Coat - Prindf and apply 1/2			
15629.63	3	side	ton, 1/4	
		CR 20-23 1/2 3,16,187		
Tot				1905358

Continuation

Particulars

Continuatic

Rf 6888148f

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
119	Pond of 72 x 100 Large Band of 2 Miles				
2	wide 700 ft x 46				
	CR 10174 = 38 each 20349				
4/13	Pond of 600 x 450 Trapezoidal Band				
11	wide 700 ft x 48				
	CR 3348 = 45 each 36833				
15/14	Pond of 600 x 450 irregular Band				
4	wide 700 ft x 48				
	CR 3539 = 91 each 14160				
16/15	Pond of 600 x 450 Rectangular Irregular Band				
8	wide 700 ft x 48				
	CR 3415 = 56 each 27324				
17/16	Pond of 72 x 100 Band of 2 Miles				
7	wide 700 ft x 48				
	CR 604 = 28 each 42300				
18/17	Plant of Trees Side of road - 1				
82	wide 700 ft x 49				
	CR 1124 = 39 each 92200				
					7083244

Continuation

Bj 7083224/

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
9/2 Contm of Sub - Gate and outfall					
810.5m into TMB 8/4/9					
CG 163233/3					4.76680
					75100825
					167559914
Add 122 G-st-d					9071912
Add 12 L-cos +					75599
Add 122 G-st-d					
63717 as Pn (46)					
6,155 as Pn (49)					
69872					
linked to R					68533
					8611247
Less 20.0770.3900					17,28277
					6882112
					6882970
Less Pn's Payments					
TMB 8/4/9					4464945
Net No					2418168
					2418025
Net Stand					
(D) E/w 18/10.23					
15/2/24					
16/2/24					

Continuation