

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E, R.W.D, Works Division Syngu
Name of Block/Road :- Kishanpur / Paswan to PMGSY Road Noywabakher

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 179m

3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length - 179m In open Area :-
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert) - Hume Pipe Culvert

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :- Local sand bags, Brick bats etc.

(ii) Equipment/Tools Being Used in Restoration Works :- J.C.B, Tractor, Roller etc.

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

88

A. Kumar

Signature of Inspector
(Official Seal)

Executive Engineer
Rural Works Department
Work Division, Birpur