

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

पत्रांक.....319 अनु०
प्रेषक,

डिहरी/दिनांक.....19/03/24

सेवा में,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव,
ब्राडा,
ग्रामि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :-

MR New Maintenance policy-2018 में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि MR New Maintenance policy-2018 अर्न्तगत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासराज

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

19-03-24

FORM GFR 19 -A

(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)

Form of Utilisation Certificate upto the Month of March, 2024

NEW MAINTENANCE POLICY 2018 MR (3054)

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(In Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road Under MR-3054	31 09.03.2024	5795.85093	Certificate that out of Rs. 5795.85093 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 5777.37474 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 18.47619 Lacs remaining unutilized at the end of the period under.
TOTAL			5795.85093	

Certified that I have satisfied myself that the conditions on which the grand-in-aid

- 2 was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works.

[Signature]
19.03.24

D.A.O

RWD (W) Div. Dehri

[Signature]
19/03/24

Executive Engineer
RWD (W) Div. Dehri

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri

Requestion formate Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

Sl No	Package No.	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No and Date	Administrative Approval (AA)		Agreement (in Lakh)		Agreement No. and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of (B) in mm/CM	Thickness of Bitumin Layer (in mm)	Value of Bitumen Content in Percentage	Previous total amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requestion against Work Done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	Five Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RW/MO/DEH/Barrachi get to barrachi village Tal	Rajpur Road ke Barrachi get to barrachi village Tal	13121034353	31.01.23	1.300	83.356	54.94348	14.08240	RWD/CEH/V01/mh-3054/mo/2023-24/22.06.23	18.04.2024	-	3415	25 MM	5%	0.000	0.000	40.57200	

श्री 2-

विभागीय पत्रांक-प्र.3054(9) 3054-4-04/2020 वर्ग 4 5047 दिनांक 23.12.2023 के संदर्भ में

प्रतिपत्र किया जाता है कि-

1. प्रस्ताव पूर्ण पर विभागीय के माध्यम से कार्य कराया जाये और कार्य MIB में दर्ज किया गया है।
2. संशुद्धित और अंतिम अधिकांश कार्य कराया गया (100% बनाया गया) संशुद्धित अधिकांश कार्य 50% तथा अंतिम अधिकांश कार्य 10% बनाया गया तथा MIS पर Upload किया गया।

0/1601/19.03.24

D.A.O
RWD (W) Div. Dehri

EXECUTIVE ENGINEER
RWD, WORKS DIVISION,
DEHRI

16/03/24

Road Name- Rajpur Road Ke Baradhi get To baradhi village Tak

Contractor Name- Sushma Associates Private Limited

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
19/3/24	15:38:19	33	0.1	270	20.2	2700	3115	G	24.97629	84.18584	Normal
19/3/24	15:38:50	33	0.1	290	20.2	2900	3315	G	24.97587	84.18593	Normal
19/3/24	15:39:11	33	0.1	280	20.2	2800	3215	G	24.97577	84.18609	Normal
19/3/24	15:39:49	33	0.1	320	10.1	3200	3615	G	24.97565	84.18647	Normal
19/3/24	15:40:25	33	0.1	350	10.1	3500	3915	G	24.97559	84.18677	Normal
19/3/24	15:40:58	33	0.1	350	20.2	3500	3915	G	24.97557	84.18689	Normal
19/3/24	15:41:30	33	0.1	340	20.2	3400	3815	G	24.97547	84.18726	Normal
19/3/24	15:41:51	33	0.1	330	20.2	3300	3715	G	24.97541	84.18755	Normal
19/3/24	15:42:23	33	0.1	320	20.2	3200	3615	G	24.97533	84.97533	Normal
19/3/24	15:42:54	33	0.1	310	30.3	3500	3915	G	24.97522	84.18810	Normal
19/3/24	15:43:19	33	0.1	280	20.2	3200	3615	G	24.97511	84.18851	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

IRI Value

Average IRI- 3615

[Signature]
19/03/24
7E

[Signature]
19-03-24
A.E.

[Signature]
19/03/24

Name of Customer :
 Name of Work/ Road :
 Lab Job number :
 Date :
 Section No. :


Test Date :
 Machine No :
 Start S No :
 Start E No :
 Weather :
 Start Location :
 End Location :
 Road Name :
 Road Type :
 Side :
 U/V Range :
 Dist Range :
 Equation :

Print Generate Report and Graph

Redraw Graph

Map View

File C:\Users\BIPRAJ\Desktop\2023\Bump Report\susma report new\hemant\papur Road Ke Baradi get To
 Name of Customer : Name of Work/ Road : Lab Job number :



19/03/24
 A.E.

19/03/24
 A.E.

19/03/24