

5th year maintenance

40

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work	Tilak Park me				
	vignad Papanam ke ghar				
	to Madhya vidyalaya				
	Tilak Park				
Agency Name	chandra kishor singh				
Agreement	47/SRD/2018-2019				
Actual comp. date	5/12/2018				
	Measurement				
(1) Restoration of Rain cuts					
	2X	2.5X	0.90X	0.30	1.35m ³
	4X	5.0X	0.80X	0.40	6.40m ³
	3X	6.0X	0.75X	0.30	4.05m ³
	4X	2.0X	0.75X	0.40	2.4m ³
	5X	3.5X	0.80X	0.35	4.90m ³
	2X	2.5X	0.75X	0.30	1.125m ³
	It = 20.05m ³				20.225m ³
(2) Maintenance of earthen shoulder					
	10X	5.0X	0.90		45.0m ²
	6X	6.0X	0.90		32.4m ²
	4X	3.5X	1.0		14.0m ²
	18X	4.0X	0.75		24.0m ²
	It = 111.38m ²				115.4m ²
(3) Maintenance of bitumen					
	Mix soil surface = bathala				
	4X	2.5X	0.75		7.5m ²
	6X	3.0X	1.0		18.0m ²
	Continuation				25.50m ²

Continuation