

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
name of work, point of road from village or place to					
return to					
Agency -	md.				
Agreement No. -	102500				mm/04/01/22
Date of start -	14.02.2021				
Actual completion -	15.02.2022				
<u>Revised Entry</u>					
1) Restoration of main					
cut with soil -					
2x	6.40	1.90	0.30		7.296
3x	5.60	1.70	0.30		8.568
4x	4.90	1.80	0.30		10.584
5x	3.90	1.60	0.30		9.36
6x	3.60	2.10	0.30		15.608
4x	4.80	1.25	0.30		7.20
6x	3.80	1.40	0.30		9.526
3x	5.55	1.10	0.20		3.62
Total:					69.8220
(2) point of contour					
skewers - 20 -					
2x 6x	6.60	2.25			178.20
2x 6x	5.80	1.80			125.28
2x 5x	6.40	1.40			89.60

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 needs — 20					
20 x 6 x 30.00 x 1.25 =					630.00
20 x 5 x 15.00 x 2.10 =					315.00
20 x 8 x 20.00 x 1.85 =					592.00
				Grand =	1537.00
18/02/23 RE			18/02/23 DN		
Abstract of Cwp					
(1) Restoration of main cuts with soil —					
69.822 m ³ made Page (41)					
at 402.90/m ³				1	28466
(2) main of barriers should —					
927.945 m ² made Page (42)					
at 60.29/m ²				1	56410
(3) main of bituminous surface —					
32.32 m ² made Page (42)					
at 282.49/m ²				1	9132

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			12.8 ft		134251
Side	0.11 ft		60/00	13 ft	148
				13	134602
<u>Sum</u> Total 1812123 DE		12.8 ft 12.8 ft			
<u>material used</u>					
Earth work -					69.82 m ²
Dimensions 5-90 -					70 m ²
2 mulch 100 ft -					10 m ²
stone chips -					0.823 m ²
crushed gravel -					0.194 m ²
<u>Sum</u> 1812123 DE					

Continuation