कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 779 विकसर

दिनांक- 02. 05. 24

प्रेषक.

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल- बक्सर

सेवा में.

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव बिहार ग्रामीण पथ विकास अभिकरण (BRRDA) बुद्ध मार्ग, पटना |

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में | महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मित (बिहार ग्रामीण पथ अनुरक्षण नीति-2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्र कर भेजा जा रहा है |

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके | अनु०- यथोक्त

विश्वासभाजन

कार्यपालक अभियंता ग्रा०का०वि०, कार्य प्रमंडल- वक्सर

02/05/24

FORM GFR 19-A

(SEE Government of india's Decision (I) below Rule-150) Form of Utilisation Certificate upto the month of March2024

MR (3054) New Maintenance Policy 2018

PJU - RWD (W), Div.- Buxar

SI. Name of No. Scheme		Amount Received (in Rs. Lacs)	Particulars
1 Construction of Rural Roads under M (3054) Mainten nce	R	10605.05398	Certified that out of Rs. 10605.05398Lacs received during the years in favour of Ex. Engineer, RWD (W), Div Buxar Bihar, a sum of Rs 10512.10560 lacs has been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs92.94834 lacs remaining unutilized at the end of the period under.
Total			

Certified that I have stisfied myself that the conditions on which the grans-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer. i.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer. ii.
- iii. Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant. iv.
- All other codal formalities have been observed.
- Physical Progress achieved :
 - i. Construction of Road works
 - ii Construction of CD works

R.W.D. (w) Div. Buxar

sition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

me of Works Division- RWD, Works Division- Buxar

	_	٦	_	_	_	Z.	1	1	1		100
	RM/BU/BU X/23/0011		23			No Package No.			-		Paris or
Simulation of the Control of the Con	RMBUBU L042-T01 TO DHANANJAYPUR X23.0011 (L42)		3			Name of Road				The second secon	
	10401902081					MIS Letter No &	Project II) as no.				The same of the same
	Letter No 6120						A Delivery	Administrative			E
	0.94			(11.00.0)	Ch KM	I amorth		Approv	Admin		
	38.049	7		(an exam)	On I akha	A		Approval (AA)	Administrative		
	25.15593 7.16600		(In Lakn)	Renewal	With Surface	Rectification	nitial	(ln l	Agreeme		
		9		(In Lakh)	Koutine	5 Years		(In Lakh)	Agreement Amount		
&13.03.2024	14/MBD/2023-24	10			Date	Agreement No. & Completion					
	12.12.2024	=		Agreement	as per	Completion IRI Bitumen Bitumen	Date Of	,			
	2347	12		mm/km)	Ē	군	Value of				
- 1	25 mm	13		(mmm)	Layer	Bitumen	Thickness of				
-	5.00%	и		percentage	Content in	Bitumen	Value of				
	0.0000	15		(In Lakh)	Amount	Alloted	Total	Previous			
	0.0000	. 16		(In Lakh)	as per MIS	expenditure	up- to- date Requisition				
	22 25897	17		(In Lakh)	done	expenditure against work	Requisition				
		=				Remarks					

Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
 Up- to- date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar
P2105124

26 m 5 ic

कार्यपालक अभिंयता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का०आ०स 7 है विनांक 02.05.24


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L042-T01 TO DHANANJAYPUR (L42) पथ का कार्य गुणवत्ता एंव विशिष्ट्यों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुरत की जाँच मेरे द्वारा 10 प्रतिशत एंव सहायक अभियंता एंव कनीय अभियंता के द्वारा शत् प्रतिशत किया गया है।

कनीय अभियंता ग्रामीण कार्य विभाग कार्य अवर प्रशाखा सिमरी कार्य अवर प्रमंडल सिमरी

सहायक अभियंता ग्रामीण कार्य विभाग

है_{2:03}.24 कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल, बक्सर



£2:05.27

Name of Road:-L042-TO1 TO DHANJAYPUR NAME OF CONTRACTOR-M/S DEVTA PROJECTS BULIDERS Date Time Section Length Bumps Speed OR IRI.TEGORY Latitude ongitude Event

							.940	Length 0.940		
	25.62179 84.11983 Normal	25.62179	1799 G	1900	10.1	190	0.04	96	16: 5: 0	30/4/24
Machine ID=415		25.62217		2400	10.1	240	0.1	96	16: 4: 18	30/4/24
IRI VALUE=2347	25.62303 84.11929 Normal I	25.62303		2000	10.1	200	0.1	96	16: 4: 0	30/4/24
<4000 4001-5000 >5001		25.62394		2900	10.1	290	0.1	96	16: 3: 43	30/4/24
Good Average Poor	25.62486 84.11951 Normal (25.62486		2700	10.1	270	0.1	96	16: 3: 8	
(R) RURAL ROAD		25.62577	2778 G	3100	10.1	310	0.1	96	16: 3: 8	
	25.62667 84.11988 Normal	25.62667		2500	10.1	250	0.1	96	10: 2: 33	20/4/24
	25.62756 84.11993 Normal	25.62756		2600	10.1	260	0.1	9 9	10. 2: 0	20/4/20
Y = 1799	25.62848 84.11997 Normal	25.62848	2207 G	2400	10.1	240	0.1	e e	16: 2: 0	30/4/24
X = 1636	25.62941 84.11998 Normal	25.62941	1636 G	1700	10.1	170	0.1	2 4	16: 2: 0	30/4/24
$Y = 0 * X ^2 + 0.816 * X + 249$			mm/km ROAD	mm/km	Rate		iii Km	R	16: 1: 22	30/4/24
	ongitude Event	Latitude.	IKI. I EGOKY Latitude ongitude	2	oped	7			20	

15. 5. ch

12.50.20