

2nd year maintenance

-51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road:- Mauna Chowk Javang lamped road to Mahora Mali talu					
Name of Agency:- Rameshwar Singh.					
Agreement No:- 24588/2019-to					
Date of Start:- 21.01.2020					
Date of Comp:- 20.01.2021					
Actual Date of Comp:- 28.05.2020					
Detailed of measurement.					
Restoration of rain cuts.					

$$4 \times 1.80 \times 1.20 \times 0.300 = 2.60m^3$$

$$6 \times 3.50 \times 1.50 \times 0.300 = 9.45m^3$$

$$13 \times 4.80 \times 1.30 \times 0.300 = 24.34m^3$$

$$8 \times 2.20 \times 1.20 \times 0.300 = 9.22m^3$$

$$17 \times 1.90 \times 0.80 \times 0.300 = 7.75m^3$$

$$9 \times 2.60 \times 1.40 \times 0.300 = 9.83m^3$$

$$15 \times 2.60 \times 1.10 \times 0.300 = 12.87m^3$$

$$76.06m^3$$

② Making up of Berms/Shoulder, stripping excess soil from the shoulder surface

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
A.E. Re.					69954200
Less 10% below					(2) Rs 6995000
					Rs. 68,959200
J. A.	30/01/2023				Sukhi
	I.A.				30/01/2023 A.E.

Material Statement

① Depth — 563.30 m

30/01/2023
J.E.

30/01/2023
A-E

927
30/1/23