

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of 1st year maintenance work (All 8 by 1/2 TMS)					
1/15-1 Restoration of road cut with 50s1					
P- 58 2km 1/15-1					
109.35 m ³ @ 404.06/m ³					44184=
2/15-2 making up of loss of material					
P-59 2km 2/15-2					
348.32 m ² @ 60.28/m ²					20695=
3/15-3 maintenance of Bitume surface with mineral surface					
P-59 2km 3/15-3					
47.81 m ² @ 276.48/m ²					132192
4/15-4 maintenance of Hume pipe Culvert					
P- 80 2km 4/15-4					
1 Nos @ 1166.58/eq					1167
5/15-5 maintenance of road sign					
P-60 2km 5/15-5					
0.22 km @ 1104.14/m					243=
6/15-12 maintenance of					

Continuation

Co = 79508=

Continuation