

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year Maintenance Bill					
N/W- Const. of Road from SH 57					
to Betti Marsingh Tak.					
Agency:- Pankaj Kumar					
Ag. No- 359 SBD/2021-22					
Date of Work order - 13.11.2021					
Actual date of Completion - 08.04.2023					
① Rehabilitation of rain cut					
and berms.. ab. EIS					
3 x 15.45 x 1.60 x .25 =					18.54 m ³
3 x 12.75 x 1.35 x .25 =					12.91 "
2 x 7.25 x 1.60 x .30 =					6.96 "
C. of phy =					38.41 m ³
Lt. =					35.18 m ³
2. making up berms					
and shoulder.. ab. EIS					
3 x 15.25 x 1.35 =					61.26 m ²
8 x 12.25 x 1.25 =					122.50 "
2 x 6.05 x 1.10 =					13.11 "
					197.07 m ²
Lt. =					195.47 m ²
3. Repair of Pot hole					
with mix seal surface					
(Type - B) .. ab. EIS					
2 x 5.5 x .90 =					9.90 m ²
4 x 2.05 x .95 =					7.79 "
Continuation					17.69 m ²
Lt. =					16.29 m ²

	Shoulder - do E19		
195.47 m ²			
@ 60.28/m ²	Rs	11783.0	
3.	Repair of pot hole		
	with mix seal sube		
	do E19		
16.29 m ²			
@ Rs	267.91/m ²	Rs	4364.0
4/7	Maintenance of		
	H.P Culvert.		
3 Nos			
@ 1166.58/Each	Rs	3500.0	
5/10.	Maintenance of 200 m		
	and km Post.		
0.658 km			
@ 748.22/Km	Rs	492.00	
	C.O. Rs =	34354.00	
Less 0.11% below	(-)	38.00	
	Net Rs	34316.00	
<u>Total</u>			
13.04.2024			
J.E			

Continuation