

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
side mark arrival at					
near - main road from lake					
chopra up to south corner					
sq. m. lake 87 road via stream					
to lake.					
Agency:- n/s Dharmachakra Constn					
Program - G7 SRO/0-18-19					
Date of work order:- 18/12/2018					
Actual date of compl:- 16/12/2019					
measurements of					
(1) restoration of main cut					
with soil movement - 40 comp					
$4 \times 14.2 \times 1.42 \times .25 = 20.164 \text{ m}^3$					
$2 \times 7.25 \times 1.2 \times .25 = 6.88 \text{ m}^3$					
$3 \times 12.75 \times 1.35 \times .25 = 12.91 \text{ m}^3$					
					49.954 m ³
				Lt.	41.82 m ³
2. making up beams and					
Shoulder dr E19					
$8 \times 9.25 \times .95 = 70.30 \text{ m}^2$					
$5 \times 9.2 \times .90 = 86.40 \text{ m}^2$					
$7 \times 14.25 \times 1.35 = 153.56 \text{ m}^2$					
$8 \times 6.50 \times .90 = 46.80 \text{ m}^2$					
$9 \times 11.55 \times .95 = 98.75 \text{ m}^2$					
$1 \times 12.5 \times .90 = 11.25 \text{ m}^2$					
					467.06 m ²
				Lt.	464.63
3. Maintenance of work					
on the road.					

Continuation

$$5 \times 5.2 \times .75 = 19.50 \text{ m}^2$$

$$4 \times 7.5 \times .85 = 25.50 \text{ m}^2$$

Sch. XLV-Form No. 134

70

[illegible]