

M.M.G.S.Y

58D/2020-21

62EN

Schedule XLV-Form No. 134

पर न माग → अधिका

P.M.G.S.Y

कावेदक - श्री जगदगुर रिशे
कसिाट पोषाDIVISION

Manager

SUB-DIVISION

Agenda - 2158D / 2019-2020

Measurement Book

1149

Defect report -

Defect -

M.B. No - 1149

511911215

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance					
M/W: Maint of road from					
Ahimsa Photsy to Ahimsa					
Dakshin 10/9.					
M/A :- SRI - Dhar Bahadur Singh.					
A/HO :- 21 SBD/2020-2021					
Date of actual completion :- 24-6-2021					
Date of Measurement :-					
Detail/s of works					
Item No (1) :- Res/correction of					
drain cut & with soil - 40					
1 x 15.00 x 1.125 x 0.30 = 5.10 m ³					
					75.98 m ³
					Limited = 75.84 m ³
Item No (2) :- Making up/over					
of materials from shoulder - 40					
10 x 30.00 x 1.125 = 337.50 m ²					
2 x 30.00 x 1.125 = 67.50 m ²					
1 x 15.00 x 1.100 = 16.50 m ²					
					421.50 m ²
					Limited = 421.31 m ²
Item No (3) :- Repair of pot					
holes with 75 mm W.D.P. - 40					
03 x 5.50 x 1.20 x 0.075 = 1.50 m ³					
2 x 10.00 x 1.50 x 0.075 = 2.25 m ³					
1 x 11.20 x 1.20 x 0.075 = 1.29 m ³					
					5.64 m ³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/P P _e 9	1127 =	
Sterno (7) :- Maint - OF					
road signs - ————					
dry videt.M.B P _{H0} (40) ie					
0.16 K.M @ P _d 1057. 19/12 M P _s 170 =					
Sterno (8) :- Maint - OF 200M					
and K.M stone - ————					
dry vide T.M.B P _{H0} (40) ie					
0.19 Km @ P _s 475 TT/K.M P _s 92 = v					
Sterno (9) :- cutting of					
branches of tree - ————					
dry vide T.M.B P _{H0} (40)					
03 Nos @ P _s 97.72/HO P _s 293 =					
Sterno (10) :- White washing					
two coats on parapet wall - ————					
dry vide T.M.B P _{H0} (40) ie					
39.00 m² @ P _s 15.94/m² P _s 622 =					
P _s 92304 =					
KERS 10% below Agg. cost → P _s 9230 =					
P _s 93074 =					
J.E					