

Ist year maintenance bills

30

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
_____					Name of road - Tongari
					Murgiya chawn to Jagdas
					Nash Panri Pmessy Park
					in Minapur block under Mmessy (NABARD)
					Agency - K.D. const, Brahampura
					P.O. - MIT, muzaffarpur
					Agreement No. - Mmessy/SD-12/18-19
					Actual date of completion
					of const. work - 20-02-2019
① Restoration of rain cuts-					
					$13 \times 1.20^m \times 1.00^m \times 0.600^m = 9.36^m^3$
					$39 \times 1.00^m \times 1.00^m \times 0.45^m = 17.55^m^3$
					$88 \times 1.00^m \times 0.90^m \times 0.30^m = 23.26^m^3$
					$39 \times 0.90^m \times 0.80^m \times 0.30^m = 8.42^m^3$
					$= 59.09^m^3$
② Maintenance of earth shoulder by filling with fertile selected soil -					
					$5 \times 30.00^m \times 1.00^m = 150.00^m^2$
					$1 \times 8.50^m \times 1.00^m = 8.50^m^2$
					$5 \times 30.00^m \times 0.90^m = 135.00^m^2$
					$1 \times 25.00^m \times 0.90^m = 22.50^m^2$
					$= 316.00^m^2$
③ Maintenance of hump					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.F R 44,798--
7) White washing of parapet of C.D. wall --					
21.96 m ² with P-37					880--
21.95 m ² limited as approx. by					
@ R 15= 63 fm ² - R 339 cor					
2) Gypsum of 200 ft ²					R 45,137--
less 10% as agreed					388--
					(-) R 4,514=0
					R 40,623--
					MJ-16-2020
					A: E:
16.02.2020					
SE mincp					

Material stations

① Soil - 91.72m3	8-18
A	
Z	
16.02.2020	