

3rd Year Maintenance

75

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Aligne of work - Maint ⁿ of Road from Pesh, Sandelpur to Manima.					
Agency - Bindu devi					
Agg. No. - 55					
(1) Restoration of Rain cuts					
10 x 5.00 x 0.90 x 300 =					13.50 m ³
6 x 7.00 x .60 x 300 =					7.56 m ³
8 x 4.00 x .50 x 300 =					4.80 m ³
6 x 9.00 x .70 x 300 =					11.34 m ³
8 x 5.00 x .40 x 300 =					9.60 m ³
					= 42.00 m ³
(2) Maint ⁿ of Earthen shoulder					
02 x 9 x 5.00 x .400 =					108.00 m ³
02 x 4 x 4.00 x .600 =					19.20 m ³
02 x 6 x 5.00 x .200 =					12.00 m ³
02 x 4 x 8.00 x .300 =					19.20 m ³
02 x 8 x 2.00 x .600 =					19.20 m ³
02 x 4 x 6.00 x .50 =					12.00 m ³
01 x 10.00 x 1.00 =					10.00 m ³
					= 199.60 m ³

Continuation

Abstract of work

78

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Rain					
		42.00m	842.94m	3202.00	
(2) Maint ⁿ of earthen					
Shoulder					
		199.60m	324m	11241.00	
(3) Repair of pots, Roly					
		23.80m ²	nde, P- (76)		
		177 = 83/m		4280 = w	
(4) Maint ⁿ of wry 483					
		23.80m	nde, P- (76)		
		177 = 83/m		4280 = w	
(5) Maint ⁿ of Patch repair					
		23.80m	nde, P- (76)		
		177 = 83/m		5054 = w	
(6) Maint ⁿ of Road Mark					
		110.00m ²	nde, P- (76)		
		177 = w/m		16700 =	
(7) Maint ⁿ of Road Mark					
		32.00m	nde, P- (76)		
		1633 = w/m		52448 = w	
(8) Maint ⁿ of Hare pipe					
		03.40m	nde, P- (77)		
		1065 = 22.40m		3197 = w	

Scanned with OKEN Scanner