

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
<u>758 year maintenance bill</u>					
<u>Name of work - Maintenance of road</u>					
<u>from 10510 Madhavali in</u>					
<u>Block - Bird</u>					
<u>Agency - Sri Abhishek Kumar</u>					
<u>Agreement No - SBD - 411/2019 - 20</u>					
<u>Date of start</u>					07/11/2019
<u>Date of completion</u>					06/11/20
<u>actual Date of completion -</u>					15/10/22
① Restoration of drain					
cut with Soil & Mud					
etc in all complete					
6x 4.0m x 3.0					
	6x	4.0m	1.20	0.30	8.64m ³
	5x	8.0m	1.0m	0.30	12.0m ³
	11x	6.0m	0.90	0.30	17.82m ³
	4x	4.0m	1.0m	0.30	4.80m ³
				Total	43.26m ³
② Maintenance of earthen					
shoulder in all					
	6x	8.0m	1.20m		57.60m ²
	9x	6.0m	1.0m		54.0m ²
	10x	7.0m	1.10m		77.0m ²
	16x	8.0m	0.80m		
	10x	8.0m	0.75m		60.0m ²
				Total	248.60m ²

Continuation

[illegible]

uatic
CO

3906820

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
				12/12	39068
(5) Main enclosure slab concrete					
width 7m3.7m x 4.6m					
qty: 0.120 x 22.91 = 44/					22912
(6) Main enclosure 2nd floor					
width 7m3.7m x 4.6m					
qty: 0.134 x 648.22 = 86.2					86.2
(7) concrete washing of parapet wall					
width 7m3.7m x 4.6m					
qty: 42.10 x 16.212 = 682.2					682.2
				7041	421242
less 10% ASP. Aggregates					42122
				7041	379122
				2011023	
				27	
Material statement					
(I) E/g : 43.26 m ³					
(II) E/g : 37.29 m ³					
(III) Stone (1/4) : 0.693 m ³					
(IV) emulsion (SS) : 0.0189 MT					
emulsion (PS) : 0.00631 MT					
(V) Bitumen : 0.0486 MT					
				2011023	
				27	

Continuation