

REO Path Lakshmi Ashan to TBI Ann Pashan house

Total Length - 3.70 K.M

Schedule XLV Form No. 134.

Mmhsy (HB)

RWD WD BIRPUR

DIVISION

BASANTPUR

SUB-DIVISION

Grobind Kumar

Ag No- 43 / S.B.D / 2019-20.

Measurement Book

730
2019-20

Grobind Kumar

Continuation

50

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

(6) White washing of Parapet walls & C.D. work

$$\text{Qty} = 4 \text{ Nos} \times 21.00 \text{ m}^2$$

$$= 84.00 \text{ m}^2$$

Muzaffar
JE 12/02/22

~~1/12/02/22~~
A.C

Material Statement

$$\text{Elw Qty} = 187.20 \text{ m}^3$$

Muzaffar
JE 12/02/22

~~1/12/02/22~~
Muzaffar

1st Year Maintenance Cost

1st on A/C Bill:-

ABSTRACT OF COST

Items of work:-

(1) Restoration of Rain Cuts

$$\text{Qty vide T.M.B P.N.D. (49)} = 187.20 \text{ m}^3$$

$$@ \text{Rs } 380.89/\text{m}^3 - \text{Rs } 71303.00$$

(2) Making up of Berm/shoulder

$$\text{Qty vide T.M.B P.N.D. (49)}$$

$$\text{Item No. (2) Qty} = 1040.02 \text{ m}^2$$

$$@ \text{Rs } 57.01/\text{m}^2 - \text{Rs } 59292.00$$

(3) Maintenance of C.D. work NPC

$$\text{Qty vide T.M.B P.N.D. (49)} = 4 \text{ Nos}$$

$$\text{Continuation } @ \text{Rs } 1106.59/\text{each} - \text{Rs } 4426.00$$

$$\text{Rs } 135021.00$$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd Year Maintenance Cost					
1st on A/c Bill:-					
Record Entry					
Name of work:- Maintenance					
of Road from REO Path Laxmikshmi					
Asthan TO Bhanu Paswan House.					
Block:- Basantpur, Supaul.					
Scheme:- Under M.M.G.S.Y (WB) 2019-20					
Agency:- Govind Kumar					
Agreement No. & Date:- 43 SBD/20-21					
Date of Maintenance:- 13-02-2022					
to 12-02-2023					
Date of Maintenance & Measurement					
Date of Entry					
Work Done:-					
(1) Restoration of Rain Cuts ---					
2 Nos x 8.00M x 0.85M x 0.300 = 4.08m ³					
6 Nos x 15M x 1.20M x 0.300M = 32.40m ³					
8 Nos x 30M x 0.85M x 0.300 = 61.20m ³					
18 Nos x 30M x 0.60M x 0.300 = 97.20m ³					
6 Nos x 30M x 0.550M x 0.300 = 29.70m ³					
Total Qty = 224.58					m ³
(2) Making up of Berm/shoulder					
2 x 18 Nos x 30M x 0.950M = 1026.00m ²					
5 Nos x 30M x 0.850M = 229.50m ²					
Total Qty = 1248.75					m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Maintenance of CD work.					
H.P. Culvert - do - do - all corners					
Qty = 4 Nos					
(4) Maintenance of Road Sign					
Qty = 3.70 KM					
(5) Maintenance of 20 CM					
And KM Stone					
Qty = 3.70 KM					
(6) Cutting of Branches of Tree					
Qty = 6 Nos					
(7) Cutting of Shrubs from roadway					
Qty = 30 Nos					
(8) Trimming of grass & weeds					
4 Nos x 30 M x 0.650 M = 74.00 m ²					
(9) White washing of Parapet wall					
Qty = 4 Nos x 21.00 m ² = 84.00 m ²					
<i>Musard</i> JE 21/1/53					
<i>Musard</i> 21/1/53					
Material Statement:-					
Flw Qty = 224.58 m ³					
<i>Musard</i> JE 21/1/53					
Continuation					
<i>Musard</i> 21/1/53					

Continuation

3rd year routine maint. 8/11/20

58

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
date -					
① Reddipath main -					
2x 20x 5.8x 1.3 x 0.30m =					106.49m ³
2x 20x 8.60x 1.50x 0.30m =					154.80m ³
					7.4m ³ = 261.29m ³
② main of shoulder repair					
2x 25x 12.60x 1.50m =					945.0m ²
2x 20x 10.50x 1.20m =					504.0m ²
					1449.0m ²
					1436.88m ²
③ main of 10' 4" of repair -					
20x 1.0x 10.38 x 0.075m =					15.57m ³
					15.56m ³
④ main of patch repairs					
2x 20x 10.0 x 0.52m =					208m ²
					207.42m ²
⑤ main of CD -					
(i) HPC - 6x1 = 6 No.					
(ii) slab cut out - 2x1 = 2 No					
⑥ main of faced ginge -					
2x 700x 0.0 = 0.00m					

Continuation

Continuation

Continuation