

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance fee					
Maint. of work - Maintenance of road					
from Kumbhari Garbadahi					
patyke Manpur palani' pazahe					
Ke Nekar to chak Dargahki					
Agency - Ashok Kumar					
Agreement No - SBD - 52/ 2019-20					
Date of commencement					18/11/19
Date of completion					17/08/20
Actual date of completion					24/09/20
(1) Restoration of Roadcut					
6x 2.0m x 1.10x 0.30					= 13.86 M ³
(2) Maintenance of earthy Shole					Gravel = 9.92 M ³
6x 4.0m x 1.0m					24.0 M ²
5x 3.0m x 0.60m					9.0 M ²
4x 3.0m x 1.0m					12.0 M ²
(3) Repair of pot-holes					4.5 M ²
filled with 75 mm size					
1x 0.1					
16x 3.0m x 1.0m x 0.07m					3.60 M ³
6x 4.0m x 1.10x 0.07m					1.98 M ³
7x 3.0m x 1.20x 0.07m					1.89 M ³
5x 3.0m x 1.20x 0.07m					3.15 M ³
					TOTAL 10.62
					Gravel 9.84 M ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) repair of pot-holes filled					
curbs 25MM 31715 cu					
6x 4.0M x 0.40 x 0.03					
2x 4.0M x 0.60 x 0.03 = 0.36 m ³					
4x 2.0M x 0.39 x 0.03 = 0.354 m ³					
				total	0.714 m ³
(4) patch patch repair over					
pot-holes 20MM present					
correction in cu					
4x 2.0 x 1.10 M = 8.80 M ²					
2x 2.0M x 0.20 M = 0.80 M ²					
				total	9.60 M ²
(5) patch repair over bitumen					
Surface curbs 20M present					
& seal coat in cu					
Area 8.80 M ² (4) = 9.60 M ²					
(6) Maintenance of road/sim: 0.05 KM					
(7) Maintenance of 240M x KM					
stone					0.05 KM
See	See	See	See	See	See
30/11/24	30/11/24	30/11/24	30/11/24	30/11/24	30/11/24
AE					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
①	Restoration of Rainceft				
	Wider 7113.75 (40) dec				
q.nts:	9.92 m ³ ev	380.32 m ³	3776 = 10		
②	Maintenance of earthen				
	sheds in cell				
	Wider 7113.75 (46) dec ②				
q.nts:	45.0 m ³ ev	59.31 m ³	2569 = 10		
③	Repair of pot holes				
	Wider 7113.75 (47) dec ③				
q.nts:	0.714 m ³ ev	10484.44 m ³	7485 = 10		
④	Patch repair over pot holes				
	Wider 7113.75 (47) dec ④				
q.nts:	9.60 m ³ ev	284.34 m ³	2729 = 10		
⑤	Patch repair over telephones				
	Surface in cell				
	Wider 7113.75 (47) dec ⑤				
q.nts:	9.60 m ³ ev	302.25 m ³	2902 = 10		
⑥	Maintenance of road sign				
	Wider 7113.75 (47) dec ⑥				
q.nts:	0.05 km ev	1074.31 km	98 = 10		
⑦	Maintenance of 210 m 8 km stone				
	Wider 7113.75 (47) dec ⑦				
q.nts:	0.05 km ev	651.45 km	33 = 10		
⑧	Cutting of Branch of tree				
	Wider 7113.75 (47) dec ⑧				

Continuation

q.nts: 0.110 ev 106.52/dec — 1062.48
 10 Total 19630 = 10

Continuation