

Sch. XLV - Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
4 th year Maintenance bill					
Name of work - to maintain					
of roof from Dha/Pur D					
Lalunagar					
Agency - Sri Ashok Kumar					
Agreement No - SRI-54/2018-19					
date of commencement - 18/02/19					
actual date of completion - 12/02/20					
① Restoration of Reticul -					
20x	4.0Mx	1.10x	0.30	26.40M ³	
18x	6.0Mx	1.10x	0.30	35.64M ³	
16x	7.0Mx	1.0Mx	0.30	33.60M ³	
17x	6.0Mx	1.0x	0.30	30.60M ³	
			total	126.24M ³	
② Maintenance of earth					
shoulder					
20x	5.0Mx	1.10M		110.00M ²	
28x	8.0Mx	1.0M		224.00M ²	
19x	9.0Mx	1.10M		188.10M ²	
16x	6.0Mx	0.98M		94.08M ²	
21x	4.0Mx	1.0M		84.00M ²	
5x	4.0Mx	1.0M		20.00M ²	
			total	720.18M ²	
③ Repair of pot holes below					
with 75mm macadam					
16x	8.0Mx	1.0Mx	0.075	9.60M ³	
④ patch repair over pot					
holes below 150mm 8cm thick					
in 150mm 8cm thick					

in Continuation

Continuation

Continuation

July: $1.614 \times 10^5 = 161,400$ — $960 = 160$

total $207852 = 207,852$

Scanned with CamScanner