

ਪੰਜਾਬੀ ਪੰਥ ਦੇ ਵਿੱਚ ਵੱਖਰੇ ਹੀਲੇ ਹੀਲੇ

MMGSy

Schedule XLV-Form No. 134

Maintenance (SC)

DIVISION

ਪੰਜਾਬੀ ਪੰਥ ਦੇ ਵਿੱਚ ਵੱਖਰੇ ਹੀਲੇ

SUB-DIVISION

MEASUREMENT BOOK

Anand Mohan ⁽⁹⁰⁷⁾ vashka

20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Paving - Path to Khinkhinda tal.					
Agency - Shri Anand Mohan Bhaskar					
Agreement No - 40/S.G.D/2018-19					
Date of start - 24/02/2019					
Date of completion - 23/02/2020					
Actual date of completion - 20/02/2020 (Record measurement)					
(1) Restoration of pavements - of d/r					
	04	0.6	$\frac{0.90+0.80}{2}$	$\times 0.30$	$= 6.12 m^3$
	05	0.7	$\frac{0.80+0.70}{2}$	$\times 0.30$	$= 9.45 m^3$
	08	0.7	$\frac{1.00+0.90}{2}$	$\times 0.30$	$= 15.96 m^3$
	03	0.5	$\frac{1.30+1.20}{2}$	$\times 0.30$	$= 5.62 m^3$
	09	0.7	$\frac{0.70+0.60}{2}$	$\times 0.30$	$= 12.28 m^3$
	04	0.6	$\frac{1.00+0.90}{2}$	$\times 0.30$	$= 6.84 m^3$
	07	0.8	$\frac{0.80+0.70}{2}$	$\times 0.30$	$= 16.2 m^3$
	10	0.7	$\frac{1.00+0.90}{2}$	$\times 0.30$	$= 19.95 m^3$
					92.42 m ³
(2) making up of beams - of E/E					
	05	0.7	$\frac{0.90+0.80}{2}$		$= 29.75 m^2$
	08	0.8	$\frac{1.10+1.00}{2}$		$= 50.4 m^2$
	07	0.9	$\frac{1.20+1.10}{2}$		$= 72.45 m^2$
	04	0.5	$\frac{1.30+1.20}{2}$		$= 25 m^2$
	09	0.9	$\frac{0.60+0.50}{2}$		$= 39.6 m^2$
	09	0.7	$\frac{0.60+0.70}{2}$		$= 40.95 m^2$

Continuation 2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	07	X 0.6	(0.90 + 0.80)	$\frac{2}{2}$	$= 35.7 m^2$
	05	X 0.4	(1.20 + 1.10)	$\frac{2}{2}$	$= 9.3 m^2$
	06	X 0.8	(1.20 + 1.10)	$\frac{2}{2}$	$= 55.2 m^2$
	06	X 0.5	(1.00 + 0.90)	$\frac{2}{2}$	$= 28.5 m^2$
	10	X 0.8	(0.50 + 0.60)	$\frac{2}{2}$	$= 4.4 m^2$
	09	X 0.7	(0.80 + 0.70)	$\frac{2}{2}$	$= 47.25 m^2$
	08	X 0.6	(0.90 + 0.80)	$\frac{2}{2}$	$= 40.8 m^2$
	09	X 0.7	(0.70 + 0.60)	$\frac{2}{2}$	$= 40.95 m^2$
					573.55 m ²
(3) Repair of pot holes 75mm — of e/r					

02	X 3.60	X 2.20	X 0.075	= 1.24 m ³
04	X 3.20	X 1.80	X 0.075	= 1.72 m ³
02	X 3.10	X 2.30	X 0.075	= 1.06 m ³
05	X 1.80	X 2.10	X 0.075	= 1.41 m ³
				5.43 m ³
(4) Patch repair over pot holes — of e/r				
02	X 3.20	X 1.85		= 11.84 m ²
03	X 2.20	X 1.95		= 12.87 m ²
02	X 3.30	X 2.10		= 13.86 m ²
02	X 3.65	X 1.80		= 13.14 m ²
02	X 3.50	X 2.30		= 16.1 m ²
01	X 2.20	X 2.00		= 5.28 m ²
				73.09 m ²
Continuation				

Continuation	06	3	2024
--------------	----	---	------

(Abstract of cost)

23

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of bitumen					
of e/r city wide +mb - P-20					
					$92.42 \text{ m}^2 @ 359.74/\text{m}^2 = 33247/-$
(2) making up of bearings					
of e/r city wide +mb - P-20					
					$53.55 \text{ m}^2 @ 53.91/\text{m}^2 = 2877/-$
(3) Repair of pot holes					
of e/r city wide +mb - P-20					
					$5.43 \text{ m}^2 @ 10807.26/\text{m}^2 = 58682/-$
(4) Patch repair over pot holes					
of e/r city wide +mb - P-21					
					$73.09 \text{ m}^2 @ 273.36/\text{m}^2 = 20045/-$
(5) Patch repair over bitumen					
of e/r city wide +mb - P-22					
					$73.09 \text{ m}^2 @ 288.52/\text{m}^2 = 21095/-$
(6) maintenance of c/d work					
of e/r city wide +mb - P-22					
					$2 \text{ Nos} @ 1104.35/\text{Nos} = 2209/-$
(7) maintenance of c/d work slab					
of e/r city wide +mb - P-22					
					$1 \text{ Nos} @ 2287.21/\text{Nos} = 2287/-$
(8) maintenance of Road Sign					
of e/r city wide +mb - P-22					
					$0.18 \text{ km} @ 1067.44/\text{km} = 192/-$

Continuation

Scanned with Oken Scanner