

4th year maintenance

88

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name	Bawork Bahilbasa				
	Rupnath parki Sadak to madhya				
	vidyalaya Bhawal Tal under				
	mmcsy (SC)				
2. Name	J. Agency: Radharaman				
3. Agreement no:	175/575/2019-2020				
4. Approval date:	10.07.2020				
	from schedule				
5. Actual of completion:	06.08.2020				
	measurement as below -				
	Item ① Restoration of drain cut				
	with soil - cut 10				
	1x	20.30	x 0.90	x 0.30	= 5.49

3x	18.50	x 0.75	x 0.25	= 10.926
2x	20.60	x 0.90	x 0.30	= 11.124
3x	10.50	x 0.85	x 0.30	= 8.033
3x	20.60	x 0.90	x 0.30	= 16.686
1x	22.50	x 0.90	x 0.30	= 6.075
1x	5.50	x 0.80	x 0.30	= 1.32
				Qty = 68.965
				say Qty = 68.12 m ³

② maintenance of drain				
Shoulder cut 10				
2x	20.50	x 0.80	=	32.80
3x	18.50	x 0.95	=	52.725
4x	20.60	x 0.85	=	70.04
5x	21.50	x 0.92	=	98.90
				1
Continuation				

Continuation

C. or Qty = 254.465

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.P. 848 = 91040.00
⑤ maintenance of home					
6 pipe culvert under					
848 = 6.0 new wide					
					page (90)
⑥ 117 = 0/each					6702.00
⑥ maintenance of road					
7 type culvert under					
848 = 12.0 new wide					
					T.M.B. page (90)
⑦ 2309 = 03/each					27708.00
⑦ maintenance of road					
8 8.8m culvert					
848 = 1.789 km wide					
					T.M.B. page (90)
⑧ 1074 = 51/10m					1590.00
⑧ maintenance of road					
9 8 km 8 times under					
848 = 1.789 km wide					
					T.M.B. page (90)
⑨ 735 = 27/10m					1088.00
					6128128.00
Less 10.0% below					12813.00
					6115315.00
1000					
20-10-2023					
J-E					
Continuation					

 tal
d t
ya
be