

4th year maintenance

53

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Chandigarh Pongsy Road					
Bhushan Singh ke ghar to					
Harshanda Sine Path me					
MLA fund per Takviashring					
Norina 70/ki					
Agency:- Adarsh Construction					
Agg. No:- 39 SAB/2018-19					
Date of w/o:- 31-10-2018					
Date of comp:-					
Actual Dt of cont:- 14/03/2019					

Measurement					
(1) Restoration of rain cuts					
with soft medium gravel					
-- do -- do E/I					
$1 \times 5 \times 1.10 \times 0.30 = 1.650 \text{ m}^3$					
$1 \times 6.00 \times 0.9 \times 0.30 = 1.620 \text{ m}^3$					
$2 \times 7.00 \times 0.80 \times 0.30 = 3.360 \text{ m}^3$					
$1 \times 9.00 \times 0.50 \times 0.30 = 1.350$					
$2 \times 8.00 \times 1.20 \times 0.30 = 5.760$					
					$= 13.740 \text{ m}^3$
(2) Maintenance of earthen shoulder					
-- all complete job --					
$4 \times 6.00 \times 1.10 = 26.400 \text{ m}^2$					
$3 \times 5.00 \times 0.9 = 13.500 \text{ m}^2$					

Continuation

Scanned with CamScanner