

| Particulars                              | Details of actual measurement |   |   | Contents of area |
|------------------------------------------|-------------------------------|---|---|------------------|
|                                          | No.                           | L | B |                  |
| <u>3rd year Maintenance</u>              |                               |   |   |                  |
| <u>From - 31/01/23 - 30-01-2024</u>      |                               |   |   |                  |
| <u>Name of work: Maintenance of</u>      |                               |   |   |                  |
| <u>road from Kalsahar to NH-102</u>      |                               |   |   |                  |
| <u>Agency-M/s Vinay Construction</u>     |                               |   |   |                  |
| <u>Agreement No. 11/S130/NDP/2019-20</u> |                               |   |   |                  |
| <u>Agreement Amount - 374456</u>         |                               |   |   |                  |
| <u>Date of start - 01/01/2020</u>        |                               |   |   |                  |
| <u>Date of Completion - 30/01/2021</u>   |                               |   |   |                  |
| <u>Date of measurement - 30/01/24</u>    |                               |   |   |                  |
| <u>1 Restoration of rain</u>             |                               |   |   |                  |
| <u>Cut with 2-1/2" Mason</u>             |                               |   |   |                  |
| <u>or gravel</u>                         |                               |   |   |                  |
| <u>1 x 30 x 0.76 x 0.30 = 6.84</u>       |                               |   |   |                  |
| <u>1 x 25 x 1.05 x 0.30 = 7.875</u>      |                               |   |   |                  |
| <u>3 x 10 x 2 x 0.76 x 0.30 = 13.68</u>  |                               |   |   |                  |
| <u>1 x 22.6 x 0.91 x 0.30 = 6.17</u>     |                               |   |   |                  |
| <u>1 x 19.20 x 0.91 x 0.30 = 5.24</u>    |                               |   |   |                  |
| <u>1 x 5 x 0.76 x 0.30 = 1.14</u>        |                               |   |   |                  |
| <u>40.94</u>                             |                               |   |   |                  |
| <u>Say 40.79 m<sup>3</sup></u>           |                               |   |   |                  |
| <u>2 Maintenance of</u>                  |                               |   |   |                  |
| <u>earthen shoulder</u>                  |                               |   |   |                  |
| <u>by stripping</u>                      |                               |   |   |                  |
| <u>excess soil from shoulder</u>         |                               |   |   |                  |

Continuation

87509 = 75

| Particulars | Details of actual measurement |    |    |    | Contents of area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

5 Cutting of branches  
of trees

Vide item 5 PN-49

Q.N = 2 Nos

@ 115 = 94 / m & 231 = 88

6 Maintenance of

Rune pipe Culvert

Vide item 5 PN-49

Q.N = 4 Nos

@ 1109 = 67 / Nos 4437 = 88

2 White washing two  
Coat on parapet

Vide item 6 PN-49

Q.N = 84.00 m<sup>2</sup>

@ 16 = 36 / m & 1374 = 24

93554 = 55 94349 = 84

less 10% below (-) 9434 = 78

84913 = 08

84913 = 00

84199 = 00

32/12/24  
S.E.

34/11/24  
ATK