

5th Year Maintenance Bill

48

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of block - Construction of the Road from					
Middle school Area in North Side To					
Samudayik Phawan Yadao Pata Isud					
Agency - M/s Dosh Deepak					
Agreement No - SBD-08/2018-2019					
Date of Commencement - 06.06.2018					
Date of completion - 05.03.2019					
Date of Actual completion - 05.02.2019					

Record Entry				
①	Restoration of rain cuts with Soil Measure			
	do	do	do	do
	2x	30m x 1.25m x 0.30m	21.60m ³	
	11x	5m x 1.20m x 0.30m	19.80m ³	
	7x	3m x 1.20m x 0.30m	7.56m ³	
				48.96m ³
②	Maintenance of Earthen shoulder surface			
	do	do	do	do
	2x	2x 30m x 1.25m	150.0m ²	
	2x	20m x 1.20m	48.0m ²	
	2x	15m x 1.25m	37.50m ²	
	2x	13m x 1.25m	32.50m ²	
Continuation				268.0m ²

Particulars	Details of actual measurement				Estimated in area
	No.	1	2	3	
① Restoration of earthen shoulder surface		do	do	do	
	Qty	vide TMB	Page No - 48		
	48.96m ²	ERS	352.21/-	17241	
② Maintenance of earthen shoulder surface		do	do	do	
	Qty	vide TMB	Page No - 48		
	268.0m ²	ERS	51.71/-	13853	
③ Maintenance of side work (HP culvert)		do	do	do	
	Qty	vide TMB	Page No - 49		
	01 Nos	ERS	1104.35/-	1104	
④ Maintenance of Road sign board		do	do	do	
	Qty	vide TMB	Page No - 49		
	0.11 Km	ERS	1067.44/-	11750	
⑤ Maintenance of 200m and Km stone		do	do	do	
	Qty	vide TMB	Page No - 49		
	0.18 Km	ERS	569.27/-	10250	
⑥ White washing of parapet wall		do	do	do	
	Qty	vide TMB	Page No - 49		
	20.64m ²	ERS	15.65/-	32350	

Continuation
 SPG Total 32748=0
 05.3.2024 J.E. Sumit 05/3/24 AE.