

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ist Year Maint Boi					
HIW - Jiradar Bhaibakhal					
PMC 35 Road to Bondhehatt					
H/Agency - Nippu Singh					
Agst. 16.8/5.32/11.11/20.20-21					
Date of start - 24-10-2020					
Actual Date of work - 15-5-2023					
Measurement Entry					
(1) PIV Restoration of					
rain cells with solid dds					
2 x 15m x 1.25 x 0.3					11.25m ³
2 x 10m x 1.2m x 0.3					7.5m ³
2 x 15m x 1.5 x 0.3					13.5m ³
1 x 20m x 1.25 x 0.3					7.5m ³
2 x 20m x 1.25 x 0.3					15m ³
Total Qty =					54.75m ³
(2) PIV making up beam					
and shoulder stoppage					
do - do as per list					
2 x 25m x 1.25m					62.5m ²
1 x 20m x 1.5m					30m ²
2 x 25m x 1.25m					62.5m ²
2 x 15m x 1.5m					45.0m ²
2 x 25m x 1.5m					60m ²
					200m ²
Limit Qty =					196.88m ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Abstract of work				
(1) Plv Restoration of drain					
cut with soil do-do					
	TMB P-55				
Qty =	54.75 m ³				
	@ R 404.46/m ³ R				221442
(2) Plv making up of beam					
and shoulder do-do					
	TMB P-55				
Qty =	196.88 m ³				
	@ R 60.28/m ³ R				1186720
(3) Plv Repair pot hole					
cut with soil cut do-do					
	TMB P-56				
Qty =	16 m ²				
	@ R 291.98/m ² R				467200
(4) Plv maint of C/S structure					
do-do TMB P-50					
Qty =	0.1				
	@ R 2394.96/m ² R				239500
(5) Plv maint Branch cutting					
of tree do-do					
	TMB P-56				
Qty =	2 m ²				
	@ R 113.64/m ² R				22700
					R 4130500

Continuation

Material Estimate

(1) E/W = 54.75 m^3

(2) Bitumen (1:3 of 2) 25 kg

(3) Stone dust = 0.05 m^3

(AK)

18-4-2024

Scanned by CamScanner