

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/A - Const'n of Road from Pithorapur					
Nubrahi Road to Dandeh via					
Nany's old under a mmmmm					
N/A - MG Railway Construction					
Pvt Ltd					
N/A - 75/230/2018-19					
Date of Start - 08/10/2018					
Actual Date of Comp - 12/07/2019					
(Measurement)					
(1) Restoration of Rain cut					
	5	5.30	1.20	0.30	9.54m ³
	8	4.60	1.0	0.30	11.04m ³
	2	4.20	1.20	0.30	13.68m ³
	6	5.10	1.20	0.30	11.07m ³
	10	5.30	1.20	0.30	19.08m ³
	8	4.60	1.0	0.30	11.04m ³
					Σ = 75.32m ³
					Time = 9 = 7442m ³
(2) Maintenance of Gutter Shoulder					
	12	5.50	1.20	2	77.20m ³
	10	4.30	1.10	2	47.30m ³
	8	6.30	1.0	2	50.40m ³
	6	14.40	1.20	2	51.84m ³
	24	3.20	0.90	2	69.12m ³
	8	5.30	0.90	2	29.52m ³
	2	5.50	1.20	2	13.20m ³
	8	5.50	1.20	2	19.80m ³
	12	4.20	1.10	2	61.92m ³
					Σ = 416.54m ³
Continuation Unit B = 4134m ³					

and your maidens work.

ABSTRACT OF COST.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Restoration of main cut Qty vide TMB P. NO - 50 B = 74.42 m @ 365.25/m = 27182					
⑤ Maintenance of another shoulder Qty vide TMB P. NO - 50 B = 413.44 m @ 5438/m = 22483					
③ Maintenance of bitumen surface Surfing Qty vide TMB P. NO - 51 B = 72.74 m @ 211.45/m = 15381					
④ Maintenance of bitumen surface B = 72.74 m @ 267.90/m = 19482					
② Providing and laying H.P. B = 330.80 m @ 770.48/m = 254835					
⑬ Maintenance of H.P. Culverts Qty vide TMB P. NO - 51 B = 2 Nos @ 1131.64/NO = 2263					
⑤ Maintenance of slab type Culverts - Qty vide TMB P. NO - 51 B = 8 Nos @ 2336.82/NO = 18695					
⑧ Maintenance of 20m and 15m Ave Qty vide TMB P. NO - 51 B = 1.45 km @ 728.56/km = 1202					
Total =					361860
					361568
Continuation	JES				